

T. Miss _____

OIL CONSERVATION COMMISE Santa Fe, New Mexico

REQUEST FOR (OIL)-(GAS) ALLOWABLE

It is necessary that this form be submitted by the operator before an initial allowable will be assigned to any completed oil or gas well. Form C-110 (Certificate of Compleance and Authorization to Transport Oil) will not be approved until Form C-104 is filed with the Commission. Form C-104 is to be submitted in triplicate to the office to which Form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs, New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filed during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at 60° Fahrenheit.

Hobbs, New Zexico Place				December 10, 1951					
WE ADE H	FRFRV RI	TOURSTING	AN ALLOWABLE FOR	A WELL KNOWN	AS:				
ME ANE H	EILEDI IU	SWUEDIINU I			110.	SE/4	NE/4		
Star	nolind O Company	il and G as or Operato	AN ALLOWABLE FOR Company_South I Leas	Mattix Well	No. <u></u> in	<u>SW 1/4</u>	₩ <u>1/4</u>		
			R, N.M						
Please i	ndicate	location:	Elevation_ 3247	DF Spudde	d 5/19/51 C	ompleted_	12/6/51		
			Total Depth]	-					
			Top 0i1/Gas Pa	v 9730	_Top Water P	ay			
			Initial Produc	Top Oil/Gas Pay_ 9730 Top Initial Production Test: Pump			Flow_31478 (BOPD_00 CHOSE)		
			Based or 314.78						
			Method of Test		-				
	- 22		Size of choke						
					-				
			Tubing (Size)_						
			Pressures: Tu	bing <u>600 psi</u>	Casi	1g 250_p	si		
			Gas/Oil Ratio_	572	Grav	ity_ 6	API		
				Casing	Perforations	: .			
	*****		10,250	- 10,300 4 5	Sh. Charge pe	r Foot.			
Unit le	tter:		Acid Record:				and water		
0	Commente	bee Desend		to					
Casing & Cementing Record			Gals Gals						
Size Feet Sax			Gals	to	5/		······································		
12 2/04	202	100							
13-3/8*	303 3811	400 600	Shooting Recor	4	8/				
9-5/8"			Qts Qts Qts	to	<u>s/</u>		· · · · · · · · · · · · · · · · · · ·		
7-7/0			Qts	to	s/				
7ª	10480	1250	Qts Qts	to	S/	· · · · · · · · · · · · · · · · · · ·			
_			Natural Produc						
			Test after aci						
	1		Test after act		Pump		Flowing		
Please i	ndicate	below Form	mation Tops(in c	onformance wi	th geographi	cal secti	on of state):		
LICUSC I	nurouvo								
		Southeast	ern New Mexico		Northwe	stern New	Mexico		
Υ. Anhv			T. Devonian _		T. Dio Al	amo			
f. Anhy f. Salt						f. Ojo Alamo F. Kirtland-Fruitland			
3. Salt				T. Montoya _7920 T. Farmington					
r. Yates						T. Pictured Cliffs			
f. 7 Rivers				T. McKee 8940 T. Cliff House					
f. Queen			. T. Ellenburge	T. Ellenburge9730 T. Menefee					
T. Grayburg			T. Gr. Wash		_ T. Point	T. Point Lookout			
T. San Andres <u>3880</u>						T. Mancos			
		4820							
T. Drinkard									
T. Tubbs 5840 T. Abo									
T • L.CIIII -			~ I• ~~~~~		↓ •				

т.

Т.

×

4J

12/6/51 Pipe line taking oil or gas: ___ Remarks:___ Stanolind Oil and Gas Company Company or Operator BV: (Xalph Z Senderakio Field Superintendent Position: ___ Send communications regarding well to: Ralph L. Hendrickson Name: Box 68 - Hobbs, New Mexico Address:__ APPROVED 12 - 17, 1951 OIL CONSERVATION COMMISSION By: RAG Gas in M