

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-11210
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No. 014923
Lease Name or Unit Agreement Name Plains Knight
Well No. 3
Pool name or Wildcat Fowler Paddock

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
Arch Petroleum, Inc.

Address of Operator
10 Desta Drive, Suite 420E Midland, Texas 79705

Well Location

Unit Letter L : 1980 Feet From The South Line and 760 Feet From The West Line

Section 23 Township 24S Range 37E NMPM Lea County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3225' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU 9/05/97

9/08/97

1) 150 sx below packer. Squeeze fast to 4000'. ISIP 1600 psi. WOC & tag TOC @ 3750'.

9/10/97

2) 50 sx @ 3550'. 5-1/2" stub @ 3500'. WOC. Tag TOC 3535'. Spot 55 sx. TOC @ 3405'. Pull to 2450'. Spot 35 sx. Pull to 1400'. Spot 25 sx. POOH.

9/11/97

3) Cut off Wellhead, 8-5/8", and 13-3/8". Cemented to surface. Visual confirmation. Spot 35 sx @ 350'. Install 10 sx Surface. Erect dry hole marker. RD MO.

PLUGGED AND ABANDONED WELLBORE.

All plugs Class "C" cement. 10# brine w/25@ gel per bbl between all plugs. Plug changes approved by OCD Hobbs District Office.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robin S. McCarley TITLE Technical Assistant DATE 09-22-97

TYPE OR PRINT NAME Robin S. McCarley TELEPHONE NO. (915) 685-1961

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE OCT 08 1997

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-11210
Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.	014923
Lease Name or Unit Agreement Name	PLAINS KNIGHT
Well No.	3
Pool name or Wildcat	FOWLER PADDOCK
Well Location Unit Letter L : 1980 Feet From The S Line and 760 Feet From The W Line 23 Section 24S Township 37E Range NMPM LEA County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3225 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator
ARCH PETROLEUM INC.

Address of Operator
10 DESTA DRIVE SUITE 420E

Well Location

Unit Letter L : 1980 Feet From The S Line and 760 Feet From The W Line

23 Section 24S Township 37E Range NMPM LEA County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3225 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. NDWH NU BOP. FISH TBG & PCKR OUT OF HOLE. SET CIBP @ 4750' CAPPED W/ 35' CMT. DETERMINED FREE PT IN 5 1/2" CSG @ 4675'. ND BOP. SHOOT OFF CSG @ 4675'. NU BOP. SET CMT STUB PLUG @ 4675'-50 IN & 50 OUT. SET CMT SHOE PLUG @ 3799'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 2450, 1400, & 350'. SET 10 SX CMT @ SURFACE (DISPLACE BETWEEN PLUGS W/ 10# BRINE/ 25# GEL PER BBL MUD). ND BOP & RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE SUMMER ENGINEER DATE 07-01-97

TYPE OR PRINT NAME DOUG PARKHURST TELEPHONE NO. 915-685-1961

(This space for State Use)

ORIGINAL CALLED BY CARLOS VILLANAS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: