NOP COPIES RECEIVED DIST RIBUTION CANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS IDO NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. LSF "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-85
ANTA FE NEW MEXICO OIL CONSERVATION COMMISSION ILE J.S.G.S. AND OFFICE PERATOR	Supersedes Old C-102 and C-103
ANTAFE NEW MEXICO OIL CONSERVATION COMMISSION ILE .S.G.S. AND OFFICE PERATOR	
ILE S.G.S. AND OFFICE PERATOR	Effective 1-1-65
S.G.S. AND OFFICE PERATOR	
AND OFFICE PERATOR	
PERATOR	5a. Indicate Type of Lease
PERATOR	State Fee X
SUNDRY NOTICES AND REPORTS ON WELLS	5. State Oil & Gas Lease Nc.
SUNDRY NOTICES AND REPORTS ON WELLS	
IDD NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
LSE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
WELL GAS WELL OTHER. Injector	
Lame of Civerator	8. Farm or Lease Name
Shall Oil Company	
Shell Oil Company	Langlie-Mattix Unit #
	9. Well No.
P.O. Box 1509, Midland, Texas 79702	9
ocation of Well	10. Field and Fool, or Wildcat
UNIT LETTER E . 660 FEET FROM THE West LINE AND 1980 FEET F	Innalia Matti-
FLET FROM THE MUSE LINE AND 1700 FEET F	Rom Langlie-Mattix
Nowth 00	
THE NORTH LINE, SECTION 23 TOWNSHIP 245 RANGE 37E NO	MENT (() () () () () () () () () () () () ()
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
2011/11/11/11/11/11/11/11/11/11/11/11/11/	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or	Uther Data
NOTICE OF INTENTION TO: SUBSEQUE	ENT REPORT OF:
RFORM REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON	PLUG AND ABANDONMENT
LL OR ALTER CASING	FLOG AND ABANDONMENT
	complete in Unner Owen [
OTHER	complete in Upper Queen
Describe Fregosea or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include works SEE Bill 5 1903	diana and days of the second day
work) SEE RULE 1103.	ang estimated date of starting any propose
3-04-79: Pulled prod. equipment.	· · · ·
3-05-79: Ran csg scraper to 3205'.	
3-06-79: Set CIBP @ 3210' and capped w/35' cmt. Perf'd 7" csg fr	om 31561 21601
3-07-79: Acidized perf's (3156' - 3168') w/1000 gals 15% NEA and	0 3130 - 3108 .
	frac treated same
w/10,000 gals EZE Frac - 60 -J - 337.	
3-08-79	
3-08-79 thru	
3-08-79 thru	
3-08-79 thru 3-11-79: Swabbing and testing well.	h arrah rur
3-08-79 thru	h swab run.
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after each</pre>	h swab run.
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac Note:</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after each</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac</pre>	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac Note:</pre>	
3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac <u>Note:</u> Dropped from report until permission is obtained to plug	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac Note:</pre>	
3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac <u>Note:</u> Dropped from report until permission is obtained to plug a breeby certify that the information above is true and complete to the best of my knowledge and belief.	
3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac <u>Note:</u> Dropped from report until permission is obtained to plug thereby certify that the information above is true and complete to the best of my knowledge and belief. G. W. Tullos	
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac Note: Dropped from report until permission is obtained to plug a thereby certify that the information above is true and complete to the best of my knowledge and belief.</pre>	
3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after each <u>Note:</u> Dropped from report until permission is obtained to plug. Thereby certify that the information above is true and complete to the best of my knowledge and belief. G. W. Tullos The A.M. Tullos The Senior Production Eng.	and abandon well.
<pre>3-08-79 thru 3-11-79: Swabbing and testing well. 3-12-79: In 10 hrs swabbed 90 BW while gassing slightly after eac Note: Dropped from report until permission is obtained to plug thereby certify that the information above is true and complete to the best of my knowledge and belief. G. W. Tullos</pre>	

•

CONDITIONS OF APPROVAL, IF ANY PIEL 1, SHIT

. •