Form 3160-5 (December 1989)	UNII DEPARTMEN BUREAU OF L	FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990 5. Lease Designation and Serial No.	
Do not use this f	6. If Indian, Allottee or Tribe Name		
	7. If Unit or CA. Agreement Designation		
L. Type of Well Oil Gas Well Well 2. Name of Operator	8. Well Name and No.		
2. Name of Operator <u>Texaco Ex</u> 3. Address and Telephone	C. C. Fristoe B Fed NCT-2 #3 9. API Well No.		
P.O. Box 4. Location of Well (Foota	1 10. Field and Pool, or Exploratory Area		
Unit Letter	Langlie Mattix 11. County or Parish, State		
Section 26,	Lea County, NM		
12.         CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO           TYPE OF SUBMISSION         TYPE OF ACTION			
	of Intent ent Report pandonment Notice	Abandonment Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shul-Off Conversion to Injection
13. Describe Proposed or Co	mpleted Operations (Clearly state all	Recomplet ertinent details, and give pertinent dates, including estimated d	ort results of multiple completion on Well Completion or ion Report and Log form.) ate of starting any proposed work. If well is directionally drilled.
give substitute foca	noms and measured and true vertical	depths for all markers and zones pertinent to this work.)* <u>PROPOSED_PROCEDURE</u>	
1) Inform B	LM and OCD 24 h	ours prior to commencemen	t of plugging.

- 2) MIRU, Install BOP. Rig up wireline.
- 3) Perf 2 squeeze holes at 1160'. TIH w/ work string and tag CIBP at 3170'.
  4) Load hole with salt gel mud; 10# brine and 25# gel/ Bbl. Pump 50', 10 sx class H cement on top of CIBP at 3170'. Move up hole. Pump 20 sx, 100' plug, from 2352'-2252'. Move up hole.
- 5) Establish circulation through squeeze perfs and fill casing and annulus with 425 sx. This includes 10% extra cement. Adjust volumes if needed.
- POH. Fill annulus and casing from surface with 1" tubing if necessary.
- ) Cut off wellhead and install marker. Clean location.
- Restore surface as per Federal requirements.

(see reverse)

14. I hereby certify that the foregoing is true and correct Signed DSH Johnson	Title Engr. Asst.	Date 7/24/91
(This space for Federal or State office weth Approved by	Tide	Date \$ 5-91
Conditions of approval, if any:	the second s	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulem statements or representations as to any matter within its jurisdiction.

		WELL DATA SHEET PO-113 (5/91)
OPERATOR:	Texaco E&P Inc.	Lease: <u>C.C. Fristoe B Fed NCT-2</u>
FOOTAGE LO	CATION:	Sec./Twn/Rng: <u>Unit P. Sec 26, T-24-S, R-37-E</u>
		Lea County, New Mexico
<u>SCHEMATIC</u>		<u>TABULAR DATA</u> Surface Casing: Set at <u>1110'</u>
Gr . 1110'	3172' DF	Size <u>9 5/8, 36</u> Cemented with <u>700</u> sx.
		TOC <u>surface</u> ' determined by <u>circulation</u>
	9 5/8", 36#, 700     sx, Cement Circ.	Hole Size <u>12 1/4"</u> Comp. Date <u>12-23-50</u>
: 1		Intermediate casing: Set at
Yates	CIBP, no cement 7", 20#, 425 sx,	Size <u>NONE</u> Cemented withsx.
		TOC ' determined by
		Hole Size
		Production Casing: Set at
	1102'-2302' 2447' 3242'	Size <u>7", 20#</u> Cemented with <u>425</u> sx.
		TOC <u>1975</u> determined by <u>Temp log</u>
		Hole Size <u>8 3/4"</u>
		<u>Open Hole Interval:</u>
		<u>3242</u> ' to <u>3472</u> ' Size <u>6 1/4"</u>
		Nitro Shot 310 Ots SOWE #1, 3359' - 3429'

Gr

.

PO-113 PLUG AND ABANDON DATA (5/91) OPERATOR: \_\_\_\_\_TEXACO\_E&P Inc. LEASE: <u>C.C. Fristoe B Federal NCT-2</u> #3 FOOTAGE LOCATION: 660 FSLX 660 FEL Sec./Twn/Rng: Unit P. Sec 26, T-24-S, R-37-E Casing integrity tested 3-24-83, 500 psi/15 minutes - OK \_\_\_\_\_Lea County, New Mexico SCHEMATIC PLUGGING DATA Surface Plug: 3188' DF Size <u>1160'-surf.</u> Cemented with <u>425</u>sx. Includes 10% extra cement volume. Class 'H' Cement, 1.18 cu ft/ sx . 1110 1160'-surface, 425 sx Intermediate Plug(s): TOC, Temp survey. 100' plug, 20 sx 1975 . 2302' 553 Size 2352'-2252' Cemented with 20 sx. Class 'H' cement, 1.18 cu ft/ sx Surface plug covers top of salt section. Intermediate plug covers base of salt. 3170' CIBP, add 50' cem. 3242' . 3472' Producing Zone Plugs: <u>.</u> \_\_\_\_ Cemented with \_\_10\_\_\_sx. Size CIBP, 50' (Retainer covers base of salt section) L. Ĩ.