## NŁ Έ CO OIL CONSERVATION C 'IS\_ JN

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission of the Commission.

Indi	cate nature of rep	oort by checking below	<b>v</b> :	
REPORT ON BEGINNING DRILLING OPER	ATIONS	REPORT ON RE	PAIRING WELL	i
REPORT ON RESULT OF SHOOTING OR F	XXXX XXXX	REPORT ON PUI	LLING OR OTHERWI	SE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DE	EPENING WELL	
REPORT ON RESULT OF PLUGGING OF W	ELL			
	Tab	he Men West	T	<del></del>
<del></del>	not	bs. New Mexico	June 19th 1937	
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO.				
Gentlemen:				
Following is or entered work done a	and the results ob	tained under the head	ling noted above at	the
GYPSY DIVISION  Company or Operator	L. M. Knigh	Lease	Well No	#1. in the
NW/4of	Sec. <b>27</b>		в <b>37</b>	NMPM
The dates of this work were as follows:_				County.
Notice of intention to do the work was [				19
and approval of the proposed plan was [				
DETAILED ACCOU				<b>1</b>
Test before shot:- Swabbed 35 Test After shot:- Flowed est				
V. B. Peck Witnessed by C. C. Cummings	ime	WPLICA American diversional	T.E.	Shooter Sup
Subscribed and sworn before me thi	3	I hereby swear or affi	rm that the inform	ation given above
20th July		Name COO		4.0-
15716	·			7-
<u>C3</u>		PositionDist	rict Supt OIL C	ORPORATION
Notary	j	Representing	Company or O	GYPSY DIVISION
My commission expires February St	h., 1941.	AddressHobb		
demarks:			4, 1	
				all and
			July 1	Upand Name
			Cii & Gas I	Name nspecter

337