NO. OF COPIES RECEIVED	Form C-103
DISTRIBUTION	Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State Fee. 🗴
OPERATOR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO ADIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
WELL A WELL OTHER- Langlie Mattix Wo	Worth Unit Tract 7
2. Name of Operator	8. Farm or Lease Name
Amerada Petroleum Corporation	
3. Address of Operator	9. Well No.
P. O. Box 668 - Hobbs, New Mexico	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM	Langlie Mattix
THE EASE LINE, SECTION 27 TOWNSHIP 24-S RANGE 37-E NMPM	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Lea
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report or Ot	het Data
	REPORT OF:
Subsequen	REFORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
	PLUG AND ABANDONMENT
PULL OR ALTER CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Prepare well for production. Pull tubing and hydrotest. Clean out to 3493' and drill from 3493' to 3550'. Run log and acidize with 500 gals. 15% NE acid. Run production equipment.

Note: This well is now temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED - Contraction	TITLE Asst. Dist. Supt.	DATE 9-10-68
APPROVED BY	TITLE	DATE