

Place Big Spring, Texas
Date July 21, 1939

Oil Conservation Commission
Box 1545
Hobbs, New Mexico

NOTICE OF COMPLETION OF: (lease) Woolworth Well NO. 7
660 Feet from east line; 660 Feet from south line;
S.T. & R. 28-248-37E

DATE STARTED May 15, 1939
DATE COMPLETED July 18, 1939
ELEVATION 3200
TOTAL DEPTH S.L.M. 3526'
CABLE TOOLS Yes : ROTARY TOOLS _____

CASING RECORD			
SIZE	<u>13" OD</u>	DEPTH	<u>124'</u>
		SAX CEMENT	<u>100</u>
SIZE	<u>8 5/8" OD</u>	DEPTH	<u>1428'</u>
		SAX CEMENT	<u>175</u>
SIZE	<u>5 1/2"</u>	DEPTH	<u>3273</u>
		SAX CEMENT	<u>100</u>

TUBING RECORD
SIZE 2" Upset DEPTH 3,519'

ACID RECORD
NO. GALS _____
NO. GALS _____
NO. GALS _____

SHOOTING RECORD
NO. QTS. _____
NO. QTS. _____
NO. QTS. _____

FORMATION TOPS
Anhydrite 1425
Top Salt 1464
Base Salt 2500
Red Sand 2890
Brown Lime 3300
White Lime 3337
Oil or Gas Pay 3438
Water None

INITIAL PRODUCTION TEST 305 in 21 hours PUMPING _____ FLOWING Yes
TEST AFTER ACID OR SHOT _____

INITIAL GAS VOLUME..... 411750

SCHEDULE NO. _____ DATE August 1, 1939

PIPE LINE TAKING OIL Shell Oil Company, Inc.

REMARKS _____ COMPANY Schermerhorn Oil Corporation

By: _____

J. P. Roberts
Superintendent.

1. The first step in the process of the development of a new product is the identification of a market need. This is often done through market research, which can be conducted in a variety of ways, including surveys, focus groups, and interviews. The goal is to understand what customers want and need, and to identify any gaps in the current market.

[illegible]

[The page contains extremely faint, illegible text, likely bleed-through from the reverse side.]

[illegible][illegible]