

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Amerada Petroleum Corporation</b>		8. Farm or Lease Name <b>Langlie Mattix Woolworth Unit</b>
3. Address of Operator <b>P. O. Box 668 - Hobbs, New Mexico</b>		9. Well No. <b>103</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1650</b> FEET FROM THE <b>North</b> LINE AND <b>2310</b> FEET FROM THE <b>West</b> LINE, SECTION <b>28</b> TOWNSHIP <b>24-S</b> RANGE <b>37-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Langlie Mattix</b>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

**Temporarily Abandoned**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cleaned out, deepened and mill on junk 3446' to 3638'. Ran Caliper log 3444' to 3600'. Ran tubing to 3615', pumped 350 sacks cement to plug back and side-track junk. Stuck tubing - unable to reverse. Top of cement 1536', backed off and washed over tubing, 1509' to 1650'. Cut tubing at 1644' and recovered. Washed over tubing 1650' to 1757'. Wash pipe torquing, pulled wash-over assembly and temporarily abandoned. No change in status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]*

TITLE **District Superintendent**

DATE **12-17-68**

APPROVED BY *[Signature]*

TITLE *[Signature]*

DATE                     

CONDITIONS OF APPROVAL, IF ANY: