

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved
Budget Bureau No. 42-11421

5. LEASE DESIGNATION AND SERIAL NO.

N.M. - 7486
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		N.M.F.U.
3. ADDRESS OF OPERATOR		8. FARM OR LEASE NAME
P. O. Box 460, Hobbs, New Mexico 88240		Jack A-29
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		9. WELL NO.
990' FSL & 1650' FEL of Sec. 29, T-24S		4
14. PERMIT NO.		10. FIELD AND FOOT, OR WHOLECAT
R-37E, in Lea County, N.M.		JALMGT. 10755
15. ELEVATIONS (Show whether DF, BY, CR, etc.)		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
3278' DF		Sec. 29, T-24S, R-37E
		12. COUNTY OR PARISH
		Lea
		13. STATE
		N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) Convert to Water inj ☒		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to convert this well to water injection by the following procedure. N.M. O.C.C. approved the injection of water into the Tangle-Mattie Pool with Adm. Order NO. R-3862.

Load hole with treated brine and pull tubing with packer. Cleanout open hole to T.D. (3589'). Run GR/N log. Run cement lined tubing with packer. Set packer at 3360' and place well on injection. Work to commence approx 1-16-70.

18. I hereby certify that the foregoing is true and correct

SIGNED M. E. Spall TITLE Adm. Section Chief DATE 1-13-70

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

USGS-5 FILE

*See Instructions on Reverse Side

