

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name C. D. Woolworth
3. Address of Operator P.O. Box 670, Hobbs NM 88240	9. Well No. 3
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3270' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Attempt to deepen from Jalmat to</u> <input checked="" type="checkbox"/>
			Langlie Mattix

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3300' TD in Jalmat. Pulled production equipment. Ppd 50 sx Class "C" cmt + 2% CaCl plug on bot w/tbg @ 3143'. Flushed w/2 bbls fresh wtr. Tagged plug @ 2903'. Washed out 20' frac sd. Drld 28' cmt to 2951'. Circ hole clean. Washed over 3 hrs to 2952'. Washed over to 2955'. Could not clean out deeper.

Transferred to inactive report July 31, 1979 pending economic evaluation. Work performed 7-22-79 through 7-31-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. B. Sikes, Jr. TITLE Area Engineer DATE 9-20-79

Orig. Signed by
Jerry Sexton

APPROVED BY Dist 1, Supv. TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

Expires 9/24/80

SEP 24 1979