

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|------------------------------------------------------------------------------------------------------|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. B-1327 |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name State "M" |
| 9. Well No. 3 |
| 10. Field and Pool or Wildcat Langlie Mattix and Jalmat (Yates) |
| 12. County Lea |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ WELL GAS ☐ WELL OTHER- **Dual Oil and Gas**

2. Name of Operator
Skelly Oil Company

3. Address of Operator
P. O. Box 1351, Midland, Texas 79701

4. Location of Well
UNIT LETTER **K**, **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM THE **West** LINE, SECTION **32** TOWNSHIP **24S** RANGE **37E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3249' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ OTHER **Plug & abandon Jalmat (Yates) gas zone** ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This is a dual well with Skelly Oil Company operating the Jalmat (Yates) gas zone. The Langlie Mattix zone is operated by Union Texas Petroleum as their Langlie Jal Unit Well No. 20. We propose to abandon the Jalmat (Yates) gas zone and turn over operation of the well to Union Texas Petroleum as follows:

- 1) Move in pulling unit. Pull tubing and packer.
- 2) Set retrievable bridge plug at 3200', and set packer at 2890'.
- 3) Squeeze perforations 3015-3090', 3095-3110', and 3175-3185' with 300 sacks of expanding cement. Pull packer.
- 4) Clean out to top of bridge plug and retrieve bridge plug.
- 5) Run tubing.
- 6) Connect wellhead and move out pulling unit.
- 7) Turn well over to Union Texas Petroleum, operator of Langlie Jal unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) **D. R. Crow** **D. R. Crow**

TITLE **Lead Clerk**

DATE **Feb. 26, 1973**

PROVED BY **Joe D. Ramsey**
Dist. I, Supv.

TITLE

DATE **FEB 28 1973**