## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIED RECEIVED	 
MOITUBIRTEID	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONDITIONS OF APPROVAL, IF ANY

## OIL CONSERVATION DIVISION

	1	X 2088	Form C-103
SANTA FE	SANTA FE, NEW	V MEXICO 87501	Revised 10-1-73
FILE	-		5a. Indicate Type of Lease
U.S.G.S.			State Fee X
LAND OFFICE			5. State Oil & Gas Lease No.
OF EARLOR	,		
CLUID	W NOTICES AND DEPORTS ON	I MELL C	mmmmmh
DUNDK THIS FORM FOR PRO	Y NOTICES AND REPORTS ON	MELLS BACK TO A DIFFERENT RESERVOIR,	
1.	ION FOR PERMIT -" (FORM C-101) FOR SUC	CH PROPOSALS.)	7. Unit Agreement Name
OIL GAS	other. Injection well		
2. Name of Operator	other- Injection well		8. Farm or Lease Name
2. Name of Operator	•		
Amerada Hess Corporatio	n		L. M. W. U.
. Address of Operator			
Drawer D. Monument, New	Mexico 88265		113
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	30 FEET FROM THE East	LINE AND 660 PEET PRO	Langlie Mattix 7 RO
THE South LINE. SECTIO	on 33 TOWNSHIP 24S	MANGE 37F NMPI	
	15. Elevation (Show whether	DF, RT, GR, esc.)	12. County
	عتى '3191 ap		Lea ()
16. Check	Appropriate Box To Indicate N	Nature of Notice Report of O	ther Data
	TENTION TO:		T REPORT OF:
NOTICE OF IN	TENTION TO:	308329021	TREPORT OF.
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PEGG AND ABANDON		
TEMPORARILY ABANDON		COMMENCE ORILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANE	CASING TEST AND CEMENT JOB	. П
		OTHER	
OTHER			
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent det	ails, and give pertinent dates, includir	ng estimated date of starting any proposed
work) SEE RULE 1103.			:
G1 2 - CC - 2 3			
Closed off side csq. va	lve & disconnected old 1	ine from same. Pressure	es un on esa, w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg. w/500#.
Held OK.	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es ഡാ on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg.w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csg. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csa. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on csa. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on esc. w/500#.
	lve & disconnected old 1	ine from same. Pressure	es un on esc. w/500#.
			es un on csg. w/500#.
Held OK.			es un on csa. w/500#.
Held OK.		of my knowledge and belief.	es un on esa, w/500#.
18. I hereby certify that the information	above is true and complete to the best o		DATE6-15-84
Held OK.	above is true and complete to the best of	of my knowledge and belief.	es up on csg. w/500#.

MODES COMMENT