

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address and Telephone No.

P. O. Box 3109, Midland, TX 79702 (915) 688-4438

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter O, 330 FSL, 1650 FEL
Sec. 35, Township 24-S, Range 37-E

Lease Designation and Serial No.
LC-057509

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. G.L. Erwin

"B" Fed NCT 2 #4

9. API Well No.

30-025-11358

10. Field and Pool, or Exploratory Area

Justis Montoya, North

Justis Fusselman

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Set 2 3/8" CIBP @ 5400', W-Side (Blinebry) Fill 2 3/8" Csg w/90 Sx plug 5400'-1800'. WOC Tag
- Set 2 7/8" CIBP @ 5550' Y-Side (Fusselman) Fill 2 7/8" Csg w/95 Sx plug 5550'-1800' WOC Tag
- Set 2 7/8" CIBP @ 6970', Z-Side (Devonian) Fill 2 7/8" Csg w/130 Sx plug 6970'-1800' WOC Tag
- Set 2 3/8" CIBP @ 5040' X-Side (Drinkard) Fill 2 3/8" Csg w/80 Sx plug 5040'-1800'. WOC Tag
- Cut all 4 Csgs @ 1800' L/D Csgs
- Spot 70 Sx plug 1800'-1600'. WOC Tag
- Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL
- Perf 6 holes @ 1500'. In 9 5/8" Csg Squeeze 125 Sx plug 1500'-1200' (T-Salt WOC Tag
- Perf 6 holes @ 310'. In 9 5/8" Csg. Squeeze 125 Sx plug 310'-200' (13 3/8" Shoe) WOC Tag
- 10 Sx Surf, 10'-Surf. Install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title FACILITY ENGR.

Date 2/7/01

(This space for Federal or State office use)

Approved (ORIG. SGD.) GARY GOURLEY

Title PETROLEUM ENGINEER

Date FEB 26 2001

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED

FEB 13 '01

RECEIVED
FEB 13 '01