Form 9–331 COPY 10 Dec. 1973	C), C. C. Form Approved. Budget Bureau No. 42–R1424
UNITED STALES DEPARTMENT OF THE INTERIOR	5. LEASE LC-057509
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas well other	8. FARM OR LEASE NAME <u>G. L. Erwin B Fed. NCT-2</u> 9. WELL NO.
2. NAME OF OPERATOR TEXACO Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, NM 88240	Justis Blinebry 11. SEC., T., R., M., OR BLK. AND SURVEY OR
 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	AREA Sec. 35, T-24-S, R-37-E
AT SURFACE: 660' FSL & 660' FEL AT TOP PROD. INTERVAL: Unit Letter "P" AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Lea New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3171 (DF)
TEST WATER SHUT-OFF	
PULL OR ALTER CASING PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
(other) Test for csg leak	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	lirectionally drilled, give subsurface locations and
 Rig up. Install BOP. Pull tubir Pressure test for leaks in 7" Cas Pressure test for leaks in 9 5/8" Specific procedures for cement so 	ing liner. Casing.
results of steps 2 & 3. 5. Return well to production.	
	JAN 1 8 1979
	U. S. GEOLOGICAL SURVI HOBBS, NEW NIEXICO
	이 방영은 것이 분석이 한 것으로 제가 제가 있는 것이 가 있는 것이 이 지금 것이 가 있는 것이 같이 많이.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED	t. Sup_{t} <u>1-12-79</u>
(This space for Federal or State of	fice used DDROVED
APPROVED BY	JAN 18 1979 GRS
	UNITENGINEER
•See Instructions on Reverse	Side ACTING DISTRICT ENGINEER