

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
LC-057509

6. If Indian, Allottee or Tribe Name
NA

7. If Unit or CA, Agreement Designation
NA

8. Well Name and No.
FED NCT-2 GLERWIN "B" No. 3

9. API Well No.
30-025-11364

10. Field and Pool, or Exploratory Area
Justice Waddell

11. County or Parish, State
Lea Co. New Mexico

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Texaco E&P Inc.

3. Address and Telephone No.
P.O. Box 730 Hobbs, NM 88240

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter I 1980' FSL & 330' FEL Sec. 35 Twn. 24S Range 37E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-7-94 Notify BLM of intent to plug & abandon well.

Note: This well has 5 strings of csg. in it. Note well diagram.

Z-string *N. Jones Well*

2A
Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

11-8-94 Pumped 20 bbl. down Z well & killed well.

11-8-94 Spot 40sks plug from 8260-7735'.

11-11-94 Spot 30 sks class C cmt. plug f/7735-4639'.

11-29-94 Spot 40sks class C cmt. plug f/4639-3100. Note circ. out excessive cmt. to 3100'.

V-string *Justice Waddell*

11-16-94 RUWL & set 2-3/8" CIBP @ 6900. dump 1/2 sks cmt. on CIBP @ 6900-6865'.

11-23-94 Spotted 85sks class C cmt. plug f/6052'-2908'. Note circ. out excessive cmt. to 2908'.

Y-string *Justice McKee*

11-15-94 RUWL & set 2-3/8" CIBP @ 6900. dump 1/2 sks cmt. on CIBP @ 6900-6865'.

11-30-94 RIH w/14" tub tag cmt 3522'. Notify BLM OK Spot 7sks cmt. plug f/3522-3100.

14. I hereby certify that the foregoing is true and correct

Signed *JD Calder* Title P&A Supervisor (Pool Co. Agent)

Date 12-28-94

(This space for Federal or State office use)

(ORIG. SIGNED) JOE G. LARA

Approved by
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 2/7/95

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

P.O. Box 730 Hobbs, NM 88240

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter I 1980' FSL & 330' FEL Sec.35 Twn.24S Range 37E

5. Lease Designation and Serial No.

LC-057509

6. If Indian, Allottee or Tribe Name

NA

7. If Unit or CA, Agreement Designation

NA

8. Well Name and No.

FED NCT-2 GLEWIN "B" No.3

9. API Well No.

30-025-11364

10. Field and Pool, or Exploratory Area

Justice Waddell

11. County or Parish, State

Lea Co. New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☐
- Subsequent Report
-
- ☒
- Final Abandonment Notice

TYPE OF ACTION

- ☐
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other

- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

W-string

11-19-94 Rig up on W string & kill well w/40 bbl. 10# brine. RUWL dump 3sks cmt. from 5216-5086' (on top of CIBP) @ 5216.
11-21-94 TIH w/tub tag 5216'. (did not tag cmt. at 5086) Sqz. 100sks class C cmt. f/5216-3100. WOC TIH w/tub didn't tag cmt.
11-22-94 Mix 2sks paper & 15sks fiber for lost circ. Mix & Pump 50sks class C cmt. behind LCM peel. Displace cmt. to 3100'. WOC & tag @ 3460. cmt. plug 5216-3460.
11-28-94 Spot 6sks class C cmt. plug from 3460-3100.

X-string

12-2-94 Rig up on X string. Establish inj. rate. Squeeze 50sks class C cmt. from 5279-3100. WOC & tag (Note reverse excess cmt. out to 3100')
12-8-94 to 12-10-94 TIH w/jet cutters & cut & pull 5 strings of csg. X-string cut @ 3100 2-3/8" tub.
W-string cut @ 3091' 2-3/8" tub. Y-string cut @ 3082' 2-3/8" tub. V-string cut @ 2905' 2-3/8" tub.
Z-string cut 3073' 2-3/8" tub.
12-12-94 Pick up 2-7/8" workstring tub. RIH tag csg. stumps @ 3100' mix & circ. hole w/9.5# 25#per bbl. salt gel mud. Spot 100sks class C cmt. plug from 3100-2846. WOC.

14. I hereby certify that the foregoing is true and correct

Signed JD Calder Title P&A Supervisor (Pool Co. Agent) Date 12-28-94

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

Form 3160-5
(June 1990)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC-057509
2. Name of Operator Texaco E&P Inc.	6. If Indian, Allottee or Tribe Name NA
3. Address and Telephone No. P.O. Box 730 Hobbs, NM 88240	7. If Unit or CA, Agreement Designation NA
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter I 1980' FSL & 330' FEL Sec. 35 Twn. 24S Range 37E	8. Well Name and No. FED NCT-2 GLERNIN "B" No. 3
	9. API Well No. 30-025-11364
	10. Field and Pool, or Exploratory Area Justice Waddell
	11. County or Parish, State Lea Co. NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-13-94 TIH tag top of cmt. 2846. POOH to 2425'. Spot 215 sks class C cmt. from 2425 to 1986.
 12-13-94 POOH w/tub. RUWL & perf. 1275' RIH w/CICR & set @ 1175'.
 12-14-94 Sting into CICR @ 1175'. Est. injection rate 2BPM at 300 PSI. Squeeze 120 sks class C cmt. below CICR @ 1175. cmt. plug from 1275-1175.
 12-14-94 RUWL & perf. @ 300'. Est. injection rate 2 BPM @ 100 PSI. Had full returns between 11-3/4" csg. & 16". Pump 260 sks class C cmt. down 11-3/4" csg. & circ. cmt. to surface.
 12-15-94 RIH tag cmt. @ 40'. Pump 20 sks cmt. from 40'-surface. R.D. pulling unit & cmt. Equip. Digout cellar cut off well head, cap well & install dry hole marker.
 Talked w/BLM Rep. Andy Cortez & Steve Caffey thru out job.

14. I hereby certify that the foregoing is true and correct

Signed JD Calder Title P&A Supervisor (Pool Co. Agent) Date 12-28-94

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
 Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

***See Instruction on Reverse Side**

