

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
320 N. 1st St. Dr.

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

N-M 14218

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. FEISTOE

C.C. B FED NCT 2 **

9. API Well No.

30-025-11366

10. Field and Pool, or Exploratory Area

JUSTIS TUBB, DEINKARD

11. County or Parish, State

LEA, NEW MEXICO

SUNDRY NOTICES AND RECORDS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No.

P.O. Box 3109 MIDLAND, TX (915) 688-4438

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT LETTER H, 2310' FNL, 660' FEL,
SECTION 35, TOWNSHIP 24-S, RANGE 37-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log for

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. SET CIBP NORTH (BLINERBY) @ 5335' FILL CSQ 70 SX CMT 5335'-3180'
2. SET CIBP WEST (TUBB-DRINKARD) @ 5900' FILL CSQ 75 SX CMT 5900'-3180'
3. SET CIBP EAST (FUSSELMAN) @ 6900' FILL CSQ 100 SX CMT 6900'-3180'
4. CUT 3 STRINGS CSQ @ 3180' LID CSQS. SPOT 40 SX PLUG 3180'-3080' (TAG @ 3180')
5. SPOT 50 SX PLUG 2400'-2300' (YATES).
6. PERF @ 1100', UNABLE TO PUMP INTO, SPOT 50 SX PLUG 1100'-900' (T-SALT TAG @ 900').
7. PERF @ 330', SQZ 240 SX (13 3/4 SHOE) 330'-200' WOC TAG @ 200'
8. PERF @ 50', SQZ 71 SX 50'-SURF (45/8 - 13 3/4)
9. INSTALL DRY HOLE MARKER P&A COMPLETE

Approved as to plugging of the well ~~done~~
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

VICE-PRESIDENT (915) 683-4996

Date

Date

AUG 09 200

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

3
CWW

RECEIVED
JUN 10 1966

6th & W. E. - 601 101

101 101

2000
Received
H. J. H. H.