

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Chevron U.S.A. Inc. 3. Address of Operator P.O. Box 670, Hobbs, NM 88240 4. Location of Well UNIT LETTER L, 1650 FEET FROM THE South LINE AND 330 FEET FROM West LINE, SECTION 36 TOWNSHIP 24S RANGE 37E N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 3140	7. Unit Agreement Name 8. Farm or Lease Name W.A. Ramsay (NCT-C) 9. Well No. 3 10. Field and Pool, or WHdeat Justis Blinebry 12. County Lea
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER rpr csg leak, log, add perfs, acidz. <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to locate casing leak and squeeze. Drill out retainer and cement, circulate clean and test squeeze. Drill out CIBP at 5510. Run GR-CCL-Neutron log from 6300-4650'. Perf additional Blinebry pay as per geological recommendations. Acidize new perfs w/1500 gallons 15% NEFE HCL. Swab. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abbin TITLE Staff Drilling Engineer DATE September 15, 1987

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE SEP 17 1987

CONDITIONS OF APPROVAL, IF ANY: