

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form 5-103  
Revised 1-1-89

# OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88241-1980  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

|   |
|---|
| WELL AP# NO.<br>30-025-11378  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>B-1732  |
| 7. Lease Name or Unit Agreement Name<br>Ramsey State  |
| 8. Well No.<br>5  |
| 9. Pool name or Wildcat<br>Langhe Matrix 7Rivers+Queen+Grayburg                                     |

|  |  |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) |  |
| 1. Type of Well<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   |  |
| 2. Name of Operator<br>Primal Energy Corporation   |  |
| 3. Address of Operator<br>211 Highland Cross, Suite #227, Houston, TX 77073  |  |
| 4. Well Location<br>Unit Letter <u>N</u> <u>560</u> Feet From The <u>S</u> Line and <u>1980</u> Feet From The <u>W</u> Line<br>Section <u>36</u> Township <u>24S</u> Range <u>37E</u> NMPM Lea County  |  |
| 10. Elevation (Show whether DF, PKB, RT, GP, etc.)<br>3137' RT   |  |

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG & ABANDONMENT ☒  
CASING TEST & CEMENT JOB ☐  
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

- Set 50 sx plug from 3400' to 2828'. Tag plug. Load hole w 9.5 ppg mud. (1-15-02 - procedure change approved by G. Wink)
- Spot 25 sx from 2260 to 2160. Spot 25 sx from 1225 to 1125'. Spot 25 sx from 378' to 278'.
- Spot 10 sx plug from 60' to surface. Erect marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE John Abernethy TITLE Manager, Operations and Engineering

DATE 1-22-02

TYPE OR PRINT NAME John Abernethy

TELEPHONE NO. 28-821-5600

This space for State Use

APPROVED BY Carry W. Hill  
CONDITIONS OF APPROVAL IF ANY

TITLE SUPERVISOR OF FIELD

DATE 1-22-02