

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-10
Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

Box 1980, Hobbs, NM 88241-1980

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II

Box Drawer DD, Artesia, NM 88210

DISTRICT III

1400 Pio Brazos Rd., Aztec, NM 87410

WELL API NO 30-025-11378
5 Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6 State Oil & Gas Lease No. B-1732
7 Lease Name or Unit Agreement Name Ramsey State
8 Well No. 5
9 Pool name or Wildcat Langhe Matrix 7 Rivers-Queen-Crayburg

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1 Type of Well OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2 Name of Operator Primal Energy Corporation	
3 Address of Operator 211 Highland Cross, Suite #227, Houston, TX 77073	
4 Well Location Unit Letter <u>N</u> <u>660</u> Feet From The <u>S</u> Line and <u>1980</u> Feet From The <u>W</u> Line Section <u>36</u> Township <u>24S</u> Range <u>37E</u> NMPM Lea County 10 Elevation (Show whether DF, PKB, PT, GP, etc.) 3137' RT	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL UP ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING CPNS ☐ PLUG & ABANDONMENT ☐
CASING TEST & CEMENT JOB ☐
OTHER ☐

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

1. Set CIBP at 3400'. Spot 25 sxs. Cement on top. Load hole w/9.5 ppg mud.
2. Spot 25 sx from 2260 to 2160. Spot 25 sx from 1225 to 1125'. Spot 25 sx from 378' to 278'.
3. Spot 10 sx plug from 60' to surface. Erect marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE  TITLE Manager, Operations and Engineering

DATE 11.7.91

TYPE OR PRINT NAME John Abernethy

TELEPHONE NO. 281-821-5600

(This space for State Use)


APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL IF ANY

Ramsey State #5
Lea Co., NM
Wellbore Schematic



8 5/8", 24ppf, cmt'd at 328' w/250 sx
Circ. To surface.

DV tool at 1200'

Prod. Perfs. 3425-3470'

5 1/2", 14ppf set at 3510' and cmt'd w/
300 sx. DV tool @ 1200' Cmt. Circ.