

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO.
2. NAME OF OPERATOR United States Smelting Refining and Mining Company		6. LAND ACQUISITION OR TRIBE NAME IC 02879 (4)
3. ADDRESS OF OPERATOR P. O. Box 1877, Midland, Texas 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 900' 990' FNL & 1650' FWL of Sec 1		8. FARM OR TRACT NAME Westates Federal
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FOLD AND TOOL, OR WITHDRAWAL SURVEY OR AREA 1-25-S, 37-E
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		12. COUNTY OR PARISH Lea
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent facts and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and bearing and true vertical depths for all markers and pertinent to this work.)		13. STATE New Mexico

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

OTHER

REPAIRING WELL

ALTERING CASING

ABANDONMENT

NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.

Plan to cut off 5 1/2" casing at approximately 5000' and pull same from hole. Will set 35 sacks cement plug 2300' to 2400' and 10 sacks cement plug at surface. This well was drilled to TD 8522 and plugged back to 5329' and temporarily abandoned 6-9-63. 13 3/8" casing is set @ 321' and cemented to surface. 9 5/8" casing is set @ 2344' and cemented to surface. 5 1/2" casing is set @ 7699' w/top of cement at 5000'.

Amended to require additional cement plugs as follows:

100' plug at 4 000-4000 feet or at top of 5" casing stub whichever is higher
100' plug at 3500-3700 feet.
100' plug at 5200-5400 feet.

Gel mud to be placed between plugs.

18. I hereby certify that the above is true and correct.

SIGNED

(This space for Federal or State use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY

TITLE

Production Clerk

DATE

12-6-66

DATE

RECEIVED
AS AMENDED
DEC 10 1968
A. H. GROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side