

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Hodges B
9. Well No. 5
10. Field and Pool, or Wildcat N. Justis-Devonian
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator CITIES SERVICE OIL COMPANY
3. Address of Operator P.O. Box 69, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER K 1650 FEET FROM THE South 1650 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 25S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3114' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8500', Devonian 7186--7199. We propose to plug and abandon this well in the following manner:

1. Set CIBP above Devonian perforations at approximately 7160'.
2. Dump 4 sack cement plug on top of CIBP.
3. Load hole with mud laden fluid
4. Shoot off and recover approximately 3950' 7" casing (top of cement 3990', base of San Andres 4838'.)
5. Spot a 35 sack cement plug $\frac{1}{2}$ in and $\frac{1}{2}$ out of 7" casing stub
6. Spot a 25 sack cement plug $\frac{1}{2}$ in and $\frac{1}{2}$ out of the 9 5/8" intermediate shoe.
7. Dump a 10 sack cement plug in top of 9 5/8" casing from ground level
8. Install 4" dry hole marker and clean location of all materials and debris.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ED _____ TITLE Dist. Admin. Supervisor DATE 1-14-72

OVERED BY _____
Orig. Signed by
Joe D. Ramey
Dist. I, Supv.

TITLE _____

DATE

JAN 19 1972

DITIONS OF APPROVAL, IF ANY: