Form 3160-5 (November 1994)

UNITL STATES DEPARTMENT OF THE INTERIOR

N.M. ON COMS. Division

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

BUREAU C	OF LAND	MANAGEN	MENT	Hobbs.	州州 13

SIIND	BUREAU OF LAND MAN		709	ns. 1	AW I WSAL	5. Lease NM 93		No.			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.								6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side								7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Oil Well Gas Well Other								nd No.			
2. Name of Operator								Westates Federal #5 9. API Well No.			
Breck Operating Corp.								11390			
3a. Address 76424 3b. Phone No. (include area code) P. O. Box 911 Breckenridge, Texas (254) 559-3355								ol, or Explora	tory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)								Blinebr	=		
1730' FNL & 330' FWL								rish. State			
Sec. 1-25S-37E								Lea County, New Mexico			
12. CHECK AF	PPROPRIATE BOX(ES)	TO INDI	ICATE NATUI	RE O	F NOTICE, R	EPORT, C	OR O	THER DA	ТА		
TYPE OF SUBMISSION			TY	PE O	F ACTION						
Notice of Intent	☐ Acidize	☐ De	eepen		Production (Star	/Resume)		Water Shut-	Off		
Nouce of Intent	Alter Casing	☐ Fr	acture Treat		Reclamation			Well Integri	ty		
Subsequent Report	Casing Repair		ew Construction		Recomplete			Other			
Final Abandonment Notice	Change Plans		ug and Abandon		Temporarily Ab	andon					
	Convert to Injection	☐ Pli	ug Back		Water Disposal						
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the op determined that the site is ready for final inspection.) Plugging Operations: 1. Placed 25' cement on top of CIBP 3 5260' Steve Caffey witnessed 2. Set CIBP @ 4950' plugging operations. 3. Circulate hole w/10# brine/mud 4. Spot 10 sack cement on top of CIBP. 5. Cut off 7" casing @ 997' 6. Spot 25 sack cement plug @ 2355'-2500' 7. Spot 50 sack plug @ 1055' 8. Tagged TOC @ 677'								nessed			
30	e casing @ 50'										
$10.$ Mix and α	circulate 100 sks	of ce	ement down	ı 9-	-5/8 casin	g thru-	peri	s and	circulated		
	ce. casing and weld o ill be restored i			:h B	SLM Regula	q/q	8	per	EU		
14. I hereby certify that the foregoin	ig is true and correct		1								
Name (Printed/Typed) Ernie Underwood	Title En	Engineering Technician									
Signature	Date										
<u>Einie Mole</u>	wood			7-21	-98						
	THIS SPACE	FOR FE	DERAL OR ST	TATE	OFFICE USE						
ORIG. SGD.) GARY GO	Tit	ile .	MEEP		Date	11/5 2	1998				
Conditions of approval, if any, are a certify that the applicant holds lega which would entitle the applicant to determine the ap	I or equitable title to those rig			fice							

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or traudulent statements or representations as to any matter within its jurisdiction.

10 GWW

As