

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

FE-
re-

Form approved
Budget Bureau No. 1004-011
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579(e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
National Coop. Refinery Assoc.
3. ADDRESS OF OPERATOR
415 W. Wall, Suite 2215, Midland, Texas 79701
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below)
At surface
330' FNL, 330' FWL
NW/NW Section 1
14. PERMIT NO. - 15. ELEVATIONS (Show whether DF, RT, GK, etc.)
3135' GL, 3146' KB

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Westates Federal
9. WELL NO.
6
10. FIELD AND POOL, OR WILDCAT
North Justis, McKee & Ellen
11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA
Sec 1, T-25-S, R-37-E
12. COUNTY OR PARISH
Lea
13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) Plug & Abandon Well ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The P&A of the Westates Federal Well #6 was completed 5-22-89 following the procedure below:

Plug #1 set @ 7000'-6700' with 125 sx Class H Neat Cement - Tagged @ 6700'.

Plug #2 set @ 4700'-4021' with 150 sx Class H Neat Cement.

Plug #3 set @ 2300'-2195' with 55 sx Class H Neat Cement.

Plug #4 set @ 1700'-1400' with 60 sx Class H Neat Cement.

Plug #5 set @ 50' to surface with 100 sx Class C Neat Cement.

Plugged & Abandoned well 5-22-89, Witnessed by Andy Cortez and Bill McManus with the BLM/Hobbs, New Mexico.

18. I hereby certify that the foregoing is true and correct

SIGNED Gavin A. Baze

TITLE Production Clerk

DATE 5-24-89

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

FOR
TITLE

DATE 6-1-89

*See Instructions on Reverse Side