

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP!
(Other instructions
reverse side)

TE*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579 (e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Westates Federal

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Justis Montoya, North

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 1, T-25 S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

National Coop. Refinery Assoc.

3. ADDRESS OF OPERATOR

2215 Wilco Bldg., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

SW/4 NW/4 Section 1, T-25-S, R-37-E
1620' FNL, 330' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3134' RT

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

Recomplete in Fusselman ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Westates Federal No. 8 is completed in the Montoya (Perf 7070'-7282')
and is presently shut-in, since it is no longer economical to operate.

The proposed workover is to recomplete in the Fusselman as follows:

- 1) Abandon Montoya zone by setting a CI bridge at approximately 7055' with 20' cement on top of plug.
- 2) Perforate in the Fusselman 6950', 52', 54', 56', 58', 60', 62', 64', 68', 70', 72', 74', 76', 78', with 1 hole per foot.
- 3) Swab test and acidize as required.

If the workover is successful, Westates Federal No. 8 will be a replacement well in the Fusselman for Westates Federal No. 4 which has declined in production to approx. 4 BOPD and 5 BWPD. Westates Federal No. 4 will be shut-in pending a workover in an upper pay.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. J. Johnson

TITLE

Dist. Prod. Supt.

DATE

3-4-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AB