NO. OF COPIES RECEIVED					
				Form C-103	
DISTRIBUTION				Supersedes O	
SANTA FE		NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C- Effective 1-1-	
FILE				211001110 [-]-	0.3
J.S.G.S.	- 	NOV I	5 8 16 AM 265	5a. Indicate Type	of Lease
LAND OFFICE	- 			State X	Fee
OPERATOR	+			5. State Oil & Go	
STERATOR			•	B-11303	ra Fedae 10.
				COCTTON	·····
(DC NOT USE THIS FORM	UNDRY NOTICE	S AND REPORTS ON	WELLS ACK TO A DIFFERENT RESERVOIR. A PROPOSALS.)		
	PPLICATION FOR PERMI	T - " (FORM C-101) FOR SUC	PROPOSALS.)		<u> </u>
OIL GAS E				7. Unit Agreemer	ıt Name
OIL GAS WELL WELL	OTHER-			-	
. Name of Operator				8. Farm or Lease	Name
HUMBLE DIL & REFINING COMPANY				New Mexico	State "BM"
. Address of Operator				9. Well No.	
P.O. Ben 2100,	Hebbs New	Marri co 88240		2	
. Location of Well	120000	HONT OF COUNTY		2 10, Field and Po	1971 1 - 4
-	(-		200		
UNIT LETTER M'TH	, <u>21.60</u> FE	ET FROM THE South	LINE AND 330 FEET	FROM Justis Bli	rebry
THE East LINE	. SECTION 2	TOWNSHIP 25-S	RANGE	Allilli	
	,				
	15	. Elevation (Show whether	DF, RT, GR, etc.)	12. County	Milli
		373/.11).F.	Lea	
6.	1 4		ature of Notice, Report of		
TEMPORARILY ABANDON		PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	- -	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER		PLUG AND ABANDON		- -	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	leted Operations (Cle	CHANGE PLANS	COMMENCE ORILLING OPNS.	PLUG /	AND ABANDONMENT
other 7. Describe Proposed or Comp. work) SEE RUL E 1103.		CHANGE PLANS	COMMENCE ORILLING OPNS. CASING TEST AND CEMENT JOB OTHER ils, and give pertinent dates, incl	PLUG /	AND ABANDONMENT

CONDITIONS OF AFPROVAL, IF ANY: