STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. 67 COPIES RECEIVED	
POITUBLETION	
SANTA FE	
FILE	
U.5.0.4.	
LAND OFFICE	
OPERATOR	

CONDITIONS OF APPROVAL, IF ANYI

OIL CONSERVATION DIVISION

Stuart Langlie Mattix Name of Operator Gulf Oil Corporation Address of Operator Box 670, Hobbs, NM 88240 Location of Well Unit Letter N 660 FEET FROM THE SOUTH LINE AND 1980 THE West LINE, SECTION 2 TOWNSHIP 25S RANGE 37E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3138' DF Lea Check Appropriate Box To Indicate Nature of Notice, Report or Cther Data NOTICE OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		OIL COMSLIK VA	CHON DIVISION			
SUNCY NOTICES AND RECORTS ON WELLS SCHOOL AND RECORDS ON WELLS SCHOOL AN	DISTRIBUTION	Р. О. ВО	X 2088			
Unity of the second control of the second co	SANTAFE	SANTA FE. NEW	/ MEXICO 87501		Revised 10-1-7	
SUDDEY MOTICES AND REPORTS ON WELLS THE TABLE OF THE ANALYSIS OF THE CASE OF	FILE	•	37.27.60 37.301			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS STATE CALLS OF A STATE OF	U.5.G.4.				of Lease	
SUNDRY NOTICES AND REPORTS ON WELLS "The property of the control	LAND OFFICE			State X	Foo	
SUNDRY NOTICES AND REPORTS ON WELLS "The property of the control	OPERATOR			5 State Ott & Gra	s i erise No	
SURDY NOTICES AND REPORTS ON WELLS OFFICE Water Injection Well Start Langlie Matrix Fines of Lynning Gulf of I Corporation Gulf of I Corporation Son 670, Hobbs, NM 88240 Langlie Matrix N 660 First Fable at South South List and 1980 First Fable at South South List and First Fable at South List and List				, state (11 d d 12	1,0036 1401	
Start Langlie Matrix Culf (ii) Corporation Box 670, Hobbs, NX 88240 Localized N				B-1	58+2	
Start Langlie Matrix Culf (ii) Corporation Box 670, Hobbs, NX 88240 Localized N	SUNDRY	Y NOTICES AND REPORTS ON	WELLS			
Cut of Oil Corporation Address of Country Box 670, Hobbs, NX 88240 Location of Add Hobbs, NX 882	(DO NOT USE THIS FORM FOR PROF USE "APPLICATI	POSALS TO DRILL OR TO DEFFEY OF PLUG 9 ON FOR PERMIT = 12 (FORK) C-1011 FOR SU	NACE TO A DIFFERENT RESERVOIR.			
Stuart Langlie Mattix Could (iii Corporation Box 570, Hobbs, NM 88240 Location of real Location of				7 Intl Auteement	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
Gulf Oil Corporation Gulf Oil Corporation Address of Corporation Box 670, Hobbs, NM 88240 Box 670, Hobbs, NM 88240 Location of the Section of the Secti		T7-6 T : 1 : 6 !	TY 11	1		
Address of Operation Box 670, Hobbs, NM 88240 107 10. Field and Poss, of bildion Langlie Mattix West N 660 Check Appropriate Box To Indicate Nature of Notice, Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data NOTICE OF INTENTION TO: Subsequent Report of Cher Data Countries Coun		other water injection	Merr			
Box 670, Hobbs, NM 88240 107 Location of sell West Inc. section 2 Troyants South Line and 1980 Treet room to South South Langlie Mattix West Inc. section 2 Troyants 258 Anne 37E Check Appropriate Box To Indicate Nature of Notice, Report or Citier Data NOTICE OF INTENTION TO: Subsequent Report of Chier Data County South Notice of	. Name of Operator			8. Form or Lease	Name Unit	
Box 670, Hobbs, NM 88240 107 Location of sell West Inc. section 2 Troyants South Line and 1980 Treet room to South South Langlie Mattix West Inc. section 2 Troyants 258 Anne 37E Check Appropriate Box To Indicate Nature of Notice, Report or Citier Data NOTICE OF INTENTION TO: Subsequent Report of Chier Data County South Notice of	Gulf Oil Corporat	ion				
Box 670, Hobbs, NM 88240 Location of real Line field and Prof. of Wildow Line field and Pro	. Address of Operator			9. Well No.		
Description of well with little N	P - (70 H 11 H	n. 000/0			3. "614 140.	
Mest		M 88240				
The list, section 2 townsite 255 savet 37E same. 15. Elevation (Show whether DF, RT, GR, etc.) 15. Country Lea 15						
The list, section 2 townsite 255 savet 37E same. 15. Elevation (Show whether DF, RT, GR, etc.) 15. Country Lea 15	N 6	60 South	1980	Tanglia	Innalia Mattin	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMODIAL WORK TREMODIAL WORK THE PLANS CHANGE	UNIT CETTER,	FEET FROM THE	LINE AND TOO FEET PRO	" KALLLALL	TITITITI	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMODIAL WORK TREMODIAL WORK THE PLANS CHANGE				VIIIIII.		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMODIAL WORK TREMODIAL WORK THE PLANS CHANGE	THE West LINE, SECTION	N 2 25S	RANGE 37E			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: **REFORM NUMBER OF AND ADARDON** PLUG AND ADARDON** CHANGE PLANS CHANGE P				XIIIIIII		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: **REFORM NUMBER OF AND ADARDON** PLUG AND ADARDON** CHANGE PLANS CHANGE P		15. Elevation (Show whether	DE. RT. GR. etc.)	15 County	<i>~``\-\-\+\+\+\\</i>	
Check Appropriate Box To Indicate Nature of Notice, Report or Ciner Data NOTICE OF INTENTION TO: **INTERNAL ALBERT OF INTENTION OF IN						
Check Appropriate Box To Indicate Nature of Notice, Report or Citier Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CARING PLUG AND ABANDON PLUG AND ABANDON CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CHANGE PLANS COMMERCE DRILLING OPPS. CASING TEST AND CEMENT AND CASING TEST AND CEMENT AND COMMERCE DRIVE TO COMMERCE DRIVE TO COMMERCE DATE CASING TEST AND CEMENT AND CASING THE C		7////	D. DE	Lea	VIIIIIII	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUS AND ABANDON	Check A	appropriate Box To Indicate N	Nature of Notice, Report or C	ther Data		
PLUS AND ABANDON CHANCE PLANS CHANCE PLANS CHANCE PLANS COMMERCE OFFICING CORN. CHANCE PLANS C						
PLUG AND ABANDONMENT CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CHINCH JOB CHANGE PLANS CHECK PLANS CHANGE PLANS			300324021	T KEFORT OF.		
PLUG AND ABANDONMENT CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CET CHONT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHECK CHINCH JOB CHANGE PLANS CHECK PLANS CHANGE PLANS		<u>—</u>				
OTHER CASING CASING COMPLETED CONTROLLED CON	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERI	NG CASING	
POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81.	TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG A	NO ABANDONMENT	
POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81.	PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
7. Generalized Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6. Thereby certify that the information above is true and complete to the best of my knowledge and belief. POP H			,		[v	
7. Descrite irroposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE null 1103. POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. POP H.			Crained Out		<u>\</u>	
POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6. Thereby certify that the information above is true and complete to the boat of my knowledge and belief. PDP H	OTHER					
POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6. Thereby certify that the information above is true and complete to the boat of my knowledge and belief. PDP H			<u> </u>	· 	·	
POH with tubing and packer. Clean out 3377'-3405'. GIH with packer and tubing. Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6. I hereby certify that the information above is true and complete to the best of my knowledge and belief. POD H.	work! SEE Bull E 1503.	erations (Clearly state all perlinent det	ails, and give pertinent dates, includir	is estimated date of s	tarting any proposed	
Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	2011) 122 1132 11331					
Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.						
Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.						
Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.						
Set packer at 3227'. Circulate hole. Start injection. Work performed 10-21-81. 6.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	POH with tubing a	and packer. Clean out 33	377'-3405'. GIH with pa	cker and tubi	nσ.	
6. I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
POP +	set packer at 322	7. Circulate noie. St	art injection. Work pe	riormed 10-21	-81.	
POP +						
POP +						
POP +						
POP +						
POP +						
POP +						
POP +						
POP +						
POP +						
POP +						
POP +		•				
POP +						
POP +						
POP +						
POP +	-					
POP +						
POP +						
POP +						
POP +	A I hereby certify that the information :	ahove is true and complete to the best	of my knowledge and better			
RPPite Area Engineer DATE 10-29-81	o, a noticely country that the intermetion i	is time with complete to the 398t (or my anowiedke sud benter.			
TITLE Area Engineer DATE 10-29-81						
THE ALEGINGHEEL DATE 10-29-01	1540 KLDITES	٠	Area Engineer	10	1_29_81	
		TITLE	rea Engineer	DATE	4 y - 0 1	
					1	