

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: Humphrey Queen Unit Well No. 9
Field: Langlie Mattix Queen
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

1. M.I.R.II.
2. Pull cement lined tubing & packer.
3. Plug back from 3585 to 3445 with cement.
4. Run C.L. tubing, set tension packer, & start injection.

5/16/72 J.E.M.