

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.		5a. Indicate Type of Lease State ☐ Fee ☒
1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator Mobil Producing TX. & N.M. Inc.		7. Unit Agreement Name
3. Address of Operator Nine Greenway Plaza, Suite 2700, Houston, TX 77046		8. Name of Lease Name Liberty
4. Location of Well UNIT LETTER <u>L</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> N.M.P.M.		9. Well No. 3
15. Elevation (Show whether DF, RT, GR, etc.) 3159 GR		10. Field and Pool, or Wildcat Jalmat
12. County Lea		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐
ALTERING CASING ☐ PLUG AND ABANDONMENT ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-15-83

3468 TD, 3062 PBTD, Yates perfs 2970-3062. MIRU Mayo Marrs Ut, pump 20 bbls fr wtr down 2-3/8 tbg, pickup on 2-3/8 tbg, tbg parted, P & LD 54 jts 1650', found 2-3/8 col split leaving 2-3/8 EUE 8RT pen looking up on fish @ 1650, SDFN.

2-16-83

Unload & rack 107 jts 2-3/8 N80 tbg, WIH w/5-1/2 OS, 2-19/32 gpls, BS, jars, cols, latch onto fish @ 1650, work free 1/4 hr, POH w/OS, rec & LD all of fish, total 97 jts 2-3/8 LD.

2-17-83

3468 TD, 2870 PBTD. WIH w/Baker 5-1/2 cmt ret on 2-3/8 tbg to 2875, pump 10 bbls BW thru ret, set ret @ 2875, pull out of ret, circ 5-1/2 csg w/10# gelled BW, set into ret, sqzd 60x cmt in Yates perfs 2970-3062, pull stinger out of ret & cap ret w/5x cmt, POH w/stinger, ran free pt 5-1/2 csg shot csg off 1745, work csg up hole 8' - 1/2 hr. SDFN, job witnessed by Eddy See w/NM O&G Com.

2-18-83

3468 TD, 2870 PBTD. Pmpd & worked 5-1/2 csg free, POH & LD 55 jts 5-1/2 17# 10RT csg, RIH w/2-3/8 tbg OE to 1795, spotted 50x Class C 1795-1640, pulled 2-3/8 tbg to 1200, WOC, SDFN, prep to tag plug, no witness from NM O&G Cmo.

2-19-83

3468 TD, 2870 PBTD. WOC 14 hrs, RIH w/2-3/8 tbg, tagged cmt plug 1615, POH w/2-3/8 tbg

(CONTINUED ON BACK SIDE)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. N. Heath TITLE Authorized Agent DATE 3-3-83

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAY 5 1983

CONDITIONS OF APPROVAL, IF ANY:

17. Continued

2-19-83 (Cont'd)

to 1350, spot 130 sxs Class C cmt plug, POH w/tbg, WOC 4 hrs, tagged plug @ 948, POH & LD 2-3/8 tbg, cut off well head & set 10 sx plug 10' to surface, installed marker, RD Mayo Marrs Csg Pullers 4:30 PM 2-18-83, witnessed by Eddie See, New Mexico O&G Com, well P&A.

FINAL REPORT.

RECEIVED
MAR 7 1983
O.C.D.
HOBBS OFFICE