


# SCOUT REPORT

## NEW MEXICO

### OIL CONSERVATION COMMISSION



Company ANDERSON PRITCHARD

Farm Name WELLS

Well No. 11

Land Classification P. TINTED

Sec. 4 Twp. 25 Range 37 County LEA

Feet from Line: 1650 N. S. 1980 E. W.

Elevation

Method

Contractor Herod

Scout

Spudded 10-25 Completed 12-1-39 Initial Production

Bond Status

#### Amount Casing and Cementing Record

| Size         | Feet        | Inches | Sax Cement |
|--------------|-------------|--------|------------|
| <u>7 7/8</u> | <u>444</u>  |        | <u>256</u> |
| <u>7"</u>    | <u>3394</u> |        | <u>600</u> |

#### Tubing Record

|              |             |
|--------------|-------------|
| <u>2 1/2</u> | <u>3513</u> |
|--------------|-------------|

#### ACID RECORD

Gals.

150

Top Pay 3450

TD

TA

TS

BS

TRS

TBL

TWL

#### SHOOTING RECORD

| No. of Quarts | Shot at | Feet |
|---------------|---------|------|
| No. of Quarts | Shot at | Feet |
| S/O           | S/O     | S/O  |
| S/O           | S/O     | S/O  |

| DATE                | Location                    |
|---------------------|-----------------------------|
| <u>10-18</u>        | <u>Location</u>             |
| <u>OCT 25 1939</u>  | <u>Location</u>             |
| <u>11-1</u>         | <u>1115 S</u>               |
| <u>NOV 8 - 1939</u> | <u>2943 A to G</u>          |
| <u>11-15</u>        | <u>TD 3459 L WOC</u>        |
|                     | <u>DST 3395 - 3439</u>      |
|                     | <u>No show</u>              |
|                     | <u>DST 3395 - 3459 35/6</u> |
| <u>NOV 22 '39</u>   | <u>TD 3518 S</u>            |
|                     | <u>Test</u>                 |
| <u>NOV 28 '39</u>   | <u>TD 3518 S. Test</u>      |
| <u>DEC 5 '39</u>    | <u>TD 3518 S</u>            |
|                     | <u>11-22 BOPED 2" 1/2</u>   |
|                     | <u>Thru 2" 1/2</u>          |

| DATE         | Location        |
|--------------|-----------------|
| <u>11-22</u> | <u>Location</u> |

## LOG

[illegible]