Form 9 371 (May 1963)	DEPA	UNITED 3 RTMENT OF	THE INTERI	OR SUBMIT IN TRIFLE (Other Instructions verse side)		Porm spipe Budget Bur 5. LEASE DESIGNATIO	eau No. 42-R14
CULIDAY MOTICES AND DEDODES ON WELLS						Federal - 05 6. IP INDIAN, ALBORT	2956 SE OR TRIBE NA
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)							
OIL X GAS WELL OTHER						7. UNIT AGREEMENT NAME	
WELL LA WELL LA OTHER 2. NAME OF OPERATOR						Langlie-Jal Unit 8. FARM OR LEASE NAME	
		EUM CORPORAT	ION				
3. ADDRIVES BY OFFICE TO 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.						9 Week so. 44	
1300 Wilco Building, Midland, Texas 79701 4. LOCATION OF WELL (Report Equation clearly and in accordance with any State regular metal.*						10. Field and Pool, or Wilder	
See also space 17 At surface	Lantlie-Mattix (Queen)						
						11. SEC., T., R., M., OR SURVEY OR ARE	BLK. AND
Unit Leti	ter "E". 2	:310' FNT. & 9	90			Sec. 4, T-25-	S. R-37-E
Unit Letter "E", 2310' FNL & 990' FWL 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)						12. COUNTY OR PARIS	
		32	18' DF			Lea	New Mex
16.	Check	Appropriate Bo	x To Indicate No	ature of Notice, Repor	t, or O	ther Data	
	NOTICE OF I	: OT NOTTENTE			Subsequi	ENT REPORT OF:	
TEST WATER SH	07-0FF	PULL OR ALTER O	:ASING	WATER SHUT-OFF		REPAIRING	well
FRACTURE TREAT		MULTIPLE COMPI	ETE	FRACTURE TREATMEN		ALTERING	
SHOOT OR ACIDIZ	38	ABANDON* CHANGE PLANS		(Other)	NG	ABANDONSH	ENT*
	rform Rem	edial Work		(Norz : Report	results o	of multiple completion tion Report and Log fo	on Well
17. DESCRIBE PROPOSE proposed work, nent to this wo	. If well is di	OPERATIONS (Clearly rectionally drilled, give-	y state all pertinent ve subsurface locatio	details, and give pertinen as and measured and true	t dates, l vertical	including estimated da depths for all marke	ite of starting a
 Pull tubing and clean out to TD of 3514'. Log well and perforate if necessary. Run rods & tubing and place well on production. 							
j	. Run rod	s & tubing a	nd place wel	l on produ c țion.			
							• • •
				•			
•							
						•	
		-					
			•			-	
						*	
S. I hereby cor	hat the forest	more and correct	et .				
SIGNED	fort 1.	allen	TITLE Open	cations Supt. We	stern	Area _{ATB} 2-5-	.74
(This space for F	'ederal or State	office use)			<i>U</i> & & &		

*Sae Instructions on Reverse SIMBTHUR R. BROWN

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: