STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	L	
DISTRIBUTION		
SANTA PE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

uo. or torico neceives	OIL CONSERVA	TION DIVISION			
DISTRIBUTION	P. O. BOX 2088 Form C-103				
SANTA PE	SANTA FE, NEW MEXICO 87501				
FILE	,		5a. Indicate Type of Lease		
U.S.G.S.			state Federal Fee		
LAND OFFICE	<u>.</u>	•			
OPERATOR	J ·		5; State Oil & Gas Lease No.		
	·		LC-055546		
SUNDR	Y NOTICES AND REPORTS ON	WELLS			
ING MOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPEN OR PLUG B. ION FOR PERMIT —" (FORM C+101) FOR SUC	ACR TO A DIFFERENT MESSENVOIM.			
1			7, Unit Agreement Name		
WELL X SAO WELL	OTHER-		Langlie Jal Unit		
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·		8. Form or Lease Name		
UNION TEXAS PETROLEU	M CORPORATION				
3. Address of Operator			9. Well No.		
	Ste. 500, Midland, TX 797	705	48		
4. Location of Well			10, Field and Pool, or Wildcat		
			· ·		
UNIT LETTER	980 reet from the North	LINE AND <u>660</u> PEET P	Langlie Mattix (Queen)		
1					
THE West LINE, SECTION	on <u>5</u> township <u>25S</u>	RANGE 37F NA	··· (
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
	3241' DF		Lea ())))))		
Check	Appropriate Box To Indicate N	ature of Notice, Report or	Other Data		
NOTICE OF IN	ITENTION TO:	SUBSEQUE	ENT REPORT OF:		
	i				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	_ [COMMENCE DRILLING OPHS.	PLUS AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOS			
7002 00 10100 00000			ean out & Deepen X		
OTHER					
	erations (Clearly state all pertinent deta	ils, and give pertinent dates, includ	ling estimated date of starting any proposed		
work) SEE RULE 1 (03.					
1 [rill 3 7/8" hole from 35	45-3707'			
	2. Ran GR neutron log from 3707-3100'.				
	3. Acidize perfs. 3385-3534' w/9500 gal. 7.5% HCL & nitrogen.				
4. Frac. from 3385-3707' w/30# cross linked fluid containing					
	000 SCF/bb1. N ₂ .				
	Ran GR after frāc.				
6. A	\dd perfs. @ 3335-3365' -	3 1/8" gun 2 SPF (41	holes).		
7. <i>F</i>	Acidize perfs. w/3300 gal	. 7 1/2 acid.			
	Ran rods & pump & placed				
	• • •	•			
			•		
•					
		·			

18. I hereby certify that the information above is true and	Ret. Permit Coord.	4-29-87
Orig. Signed by Paul Kautz Geologist	TITLE TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOUR	MAY 1 1907
CONDITIONS OF APPROVAL, IF ANY		

THE LEWIS OFFICE AND ASSOCIATION OF THE PROPERTY OF THE PROPER

्रेड क्रिक्स कर एक विकास क्रिक्स अक्षाना