Form 9-331 (May 1963)	UNITED S	TATES	SUBMIT IN TRIPLICAT	E. Form and	97-4 <sup>2</sup> .
		THE INTERI	OR verse side)	5. LEASE DES	
	GEOLOGICA	L SURVEY		IC-055546	•
SUN	IDRY NOTICES AND	REPORTS C	ON WELLS	6. IF INDIAN, ALLOTT	CSS OR TRIBS NAME
(Do not use this	form for proposals to drill or i Use "APPLICATION FOR PER	to deepen or plug b. RMIT—" for such pr	ack to a different reservoir. oposals)		
1.		3	18 0	7. UNIT AGREEMENT	NAME
WELL WELL	OTHER	*,		Langlie-Jal	
2. NAME OF OPERATOR				8. FARM OR LEASE N	
UNION TEX	XAS PETROLEUM CORPOR	RATION	-		
	-	1 - 46		9. WELL NO.	
4. LOCATION OF WELL (F	lco Building, Midlar Report location clearly and in acc	ordance with any	NUL	10. FIELD AND POOL.	
See also space 17 belo At surface	) <b>w.)</b>			3 3	
				Langlie Matt 11. ssc., T., R. M. OS	BLE. AND
				SURVET OR ARE	
Unit Letter '		FWL		Sec. 5, 1-25	-\$, R-37-E
14. PERMIT NO.		S (Show whether DF,	RT, CR, etc.)	12. COUNTY OR PARIS	1 3 4 5 B
	<u> </u>	.82' GR	·	Lea	New Měxico
16.	Check Appropriate Box	e To Indicate Ne	ature of Notice, Report, or	Other Data 233	្ន ខេត្តិភ្លីទី 👘
2	OTICE OF INTENTION TO:	1.1.1.1.1.1		QUENT REPORT OF:	· 파이스 등 문 문 문 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이
TEST WATER SHUT-OF	PULL OB ALTER C	ASING	WATER SHUT-OFF	BEPAIBING	
FRACTURE TREAT	MULTIPLE COMPL	ETE	FRACTURE TREATMENT	ALTERING	-
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONM	·
REPAIR WELL	CHANGE PLANS		(Other) <u>Clean out</u>		<u> </u>
(Other)			Completion or Recom	its of multiple completion apletion Report and Log fo	arm )
proposed work. If nent to this work.) *	COMPLETED OPERATIONS (Clearly well is directionally drilled, giv	e subsurface location	details, and give pertinent date ons and measured and true vert	es, including estimated da ical depths for all marke	te of starting any rs and zones perti-
		• · · · · · · ·			
· · · · · ·					
	L. March 15, 1975, r				
	2. Cleaned out well	Ŷ	-	ned to TD 3660'	(4=3/4" hole
	8. March 22, 1975, 1				
2	4. March 24, 1975, T		"C" 50/50 Pozmix and		and the second
	flake/sx.	5X. 01455	G J0/J0 FOZIELX and		47 08110-
5	5. March 26, 1975, d	rilled out o	cement to top of 4"	liner and press	s. casing to
	1000# w/no dec. i	n pressure.		·····································	
6	5. March 27, 1975, d		cement in 4" liner a	and press. line	e to 1000#
·	w/no dec. in pres		• • •		
· · · · · · · · · · · · · · · · · · ·	<ol> <li>At the present ti well.</li> </ol>	me, we are w	waiting on a comple	tion unit to cor	iplete this
	WCLL.		н. На стали стали На стали с	3월 17월 18일 1911년 - 1911년 - 1911년 1911년 - 1911년 - 1911년 1911년 - 1911년 - 1911년 1911년 - 1911년 - 1911년 1911년 - 1911년 -	
				이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이	
		·		(1997년) 1997년 - 1997년 1997년 - 1997년 - 1997년 1997년 - 1997년 - 1997년 1997년 - 1997년 - 1997년 1997년 - 1997년 - 1997년 - 1997년 - 1997년 1997년 - 1997년 - 1997년 - 1997년 - 1997년 - 1997년 1997년 - 1997년 - 1997년 - 1997년 - 1997년 1997년 - 1997년 - 19970 - 19970 - 19970 - 19970 - 19970 - 19970 - 1	
•	•	1			
-	•			· 말이 쇼프 · 안 것 같겠음 제 상	
•.	· · · ·			유리 등 한 후 (취 주 ( 취 ) 원	
•					
18. I hereby certify that t	the foregoing is true and correct				
-A-0			Maggingmont Analizat		
SIGNED Josele	4 vr. vour	TITLE Gas I	Measurement Analyst	DATE 4-4-7	
(This space for Feder	il or State office use)			ACCEPTED FO	<u>B KFCOKO  </u>
APPROVED BY	· ·	TITLE	 	DATE.	1 175 1
CONDITIONS OF APP	PROVAL, IF ANY:			APR	1213 200
	· · · ·			U. S. GEOLOGI	CAL SURVEY
		. <b>.</b> .	D	HOBBS, NE	W MEXICO
	*S	se Instructions o	in Reverse Side	11000007	

5	Instructions	on	Kever