

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-1147700
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WOOLWORTH, GR.3
8. Well No. 001
9. Pool name or Wildcat JALMAT-YATES-SR-QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>646</u> Feet From The <u>WEST</u> Line Section <u>6</u> Township <u>25-S</u> Range <u>37-E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3187.4' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: PLUG & ABANDON WELL. ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/19/96 MIRU SIERRA WS #3, PMP 10 BBLS FW DWN TBG, LOCKED UP, PMP 80 BBLS DWN CSG, STATIC, NU CL I BOP, LD 97 JTS 2.375" PROD TBG, PU CIBP & GIH W/87 JTS WS & SET CIBP @ 2750', SDON.
07/22/96 MIX & CIRC 85 BBL 10# GELLED BRINE (MLF), PMP PLUG #1 60 SX 2750'-2389', NOTE: CMT F/PLUGS CL "C" 14.8 PPG 1.32 CFPS, LD 44 JTS WS, TOH W/22 STDS, ND BOP, ND 7" WH, WELD ON 7" PULL JT, WELD ON 13.375" CSG, NU SPOOL, NU BOP, FREEPOINT STRETCH 7" CSG, FREE @ 1475', SECURE WELL, SDON.
07/23/96 RU WL TRUCK & CUT 7" CSG @ 1330', RD WL TRUCK, LD 44 JTS 7" CSG, CHG RAMS T/2.375, RD CSG PULLING EQMT, RU TBG TOOLS, TIH W/TBG T/1389', PMP PLUG #2 120 SX 1389'-991'(CALC TOC), TOH W/WS, WOC & TAG, SDON.
07/24/96 TIH & TAG PLUG #2 @ 1059', TOC @ 1059' PMP PLUG #3 35 SX 504'-398', TOH PU 9.625"
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Senior Regulation Analyst

DATE

7-25-96

TYPE OR PRINT NAME

Larry M. Sanders

TELEPHONE NO. (915)368-1488

(This space for State Use)

APPROVED BY

TITLE

DATE

JAN 28 1997

CONDITIONS OF APPROVAL, IF ANY:

WOOLWORTH G3-001

(CONTINUED)

07/24/96

CONTINUED

AD-1 RENTAL PKR & SET @ 31', TST 9.625" CSG T/250# TST OK, RU WL TRUCK & PERF @ 260' RD WL TRUCK, PMP PLUG #4 205 SX 260' - 3', CMT CIRC T/SURF LEAVING INSIDE 9.625" CSG FULL & 9.625 X 13 ANNULUS FULL, ND BOP WASH UP TOOLS & EQMT, CUT & CAP, INSTALL DRY HOLE MARKER, RDMO SIERRA WS #3 AND CMT EQMT, PERFORM RECLAMATION WORK, WELL PA'D.

COMPLETE DROP FROM REPORT

