ENERGY AND MINERALS DEPARTMENT



LARRY KEHOE SECRETARY OIL CONSERVATION DIVISION

BRUCE KING May 5, 1982

PIC BDN 1960 HOEBS NEW MEXICO 88940 (505) 393-6161

Union Texas Petroleum Company 1300 Wilco Building Midland, TX 79701

Amoco Production Company Box 68 Hobbs, NM 88240

SUBJECT: Union Texas - Langlie Jal Unit #83-L 9-25-37 (LM Inj. well)

Amoco - Langlie A Fed #2-L 9-25-37 (Jalmat Gas well)

Gentlemen:

We were unable to approve the zone segregation test submitted by Amoco on April 28, 1982, on the above-captioned well. One of our field inspectors checked the well May 4, 1982, and it appears to be communicated.

The 1980 and 1981 bradenhead tests conducted on this well indicated possible communication as well as a waterflow from the intermediate casing. Union Texas Petroleum was requested by letters dated August 21, 1980, and August 19, 1981, to make needed repairs. As indicated from the zone segregation test and the May 4, 1982 inspection of the well no repair work has been done.

You are hereby requested to shutin this well immediately and make necessary repairs. It will be necessary to notify the Hobbs District Office prior to commencing work in order that workever may be witnessed by an OCD inspector.

Since this problem has not been corrected after two requests, we are notifying the OCD attorney, by copy of this letter, and legal action may be forthcoming.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton

Supervisor, District I

JS/ED

cc: Perry Pearce - OCD General Counsel
File