

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: LANGLIE MATTIX QUEEN UNIT Well No. 6

Field: LANGLIE MATTIX

County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. MIRU CABLE TOOL RIG - PULL PRODUCING EQUIPMENT.
2. DRILL DEEPER FROM 3395' TO 3470' (75 FEET). CLEAN OUT.
3. LOG OPEN HOLE WITH GR-SONIC-CALIPER AND ANY OTHER LOG REQUESTED BY GEOLOGIST OR ENGINEER
4. G.I.H. WITH TUBING AND LYNES OPEN HOLE PACKER. SET PACKER IN GAUGE HOLE AT OR ABOUT 3395 AND ACIDIZE NEW HOLE (3395'-3470') WITH 4000 GALS. 15% NE HCL. DISPLACE ACID WITH LEASE OIL.
5. PULL TUBING AND PACKER -
6. PLACE WELL ON PRODUCTION AND TEST.

RECEIVED

JAN 15 1971

OIL CONSERVATION COMM.
HOBBS, N. M.