

CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name Stuart Langle Mattix Unit
Name of Operator Chevron U.S.A. Inc.		8. Farm or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240		9. Well No. 113
Location of Well UNIT LETTER C 990 North 1650 FEET FROM THE LINE AND FEET FROM West 10 25S 37E THE LINE, SECTION TOWNSHIP RANGE NEPM.		10. Field and Pool, or Wildcat Langle Mattix
11. Elevation (Show whether DF, RT, GR, etc.) 3134' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	☐
TEMPORARILY ABANDON	☐
ILL OR ALTER CASING	☐
OTHER Find & Repair Casing Leaks	☒

PLUG AND ABANDON	☐
CHANGE PLANS	☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK	☐
COMMENCE DRILLING OPS.	☐
CASING TEST AND CEMENT JOBS	☐
OTHER	☐

ALTERING CASING	☐
PLUG AND ABANDONMENT	☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to find and isolate casing leaks. Repair leaks as necessary. Test casing to 500 psi for 30 minutes. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

P. H. Bulley Jr.

TITLE Division Drilling Manager DATE 6-24-1986

ORIGINAL SIGNED BY JERRY SEXTON

OVER BY DISTRICT SUPERVISOR

TITLE

DATE JUN 26 1986

CONDITIONS OF APPROVAL, IF ANY: