NO. OF COPIES RECEIVED				
DISTRIBUT	ON			
SANTA FE				
FILE				
U.S.G.S.				
LAND OFFICE				
IRANSPORTER	PORTER OIL			
THANSI ON EN	GAS			
OPERATOR				
		1		

NEW MEXICO OIL CONSERVATION COMMISSION

	SANTA FE	REQUEST	FOR ALLOWABLE	Supersedes Old C-104 and C-110		
	FILE		AND	Effective .1-1-65		
	U.S.G.S.	AUTHORIZATION TO TRA	ANSPORT OIL AND NATURAL (SAS		
ļ	LAND OFFICE					
	TRANSPORTER OIL					
	GAS					
	OPERATOR					
1.	PRORATION OFFICE					
	Operator		-			
	Oulf Oil Corporation					
	Address	_	_1 _			
			9745			
	Reason(s) for filing (Check proper box,	•	Other (Please explain)	vline connected to		
	New Well	Change in Transporter of:	central battery	9-17-68. Change in		
	Recompletion	Oil Dry Go	Tocacion or our	storage and gas		
L	Change in Ownership	Casinghead Gas Conder	connections.			
•	If change of ownership give name and address of previous owner DESCRIPTION OF WELL AND Legse Name	LEASE Well No. Pool Name, Including F		_		
	Stuart Langlie Mattix L	hit 121 Ianglie Mat	State, Federa	cr Fee Fee		
		_		_		
ł	Unit Letter / I ; 16	50 Feet From The South Lir	ne and 990 Feet From	The East		
	_		7-770 Y a.o.			
į	Line of Section 10 Tov	vnship 25S Range	37E , NMPM, Les	County		
			_			
III.		FER OF OIL AND NATURAL GA	Address (Give address to which appro	and copy of this form is to be sent		
	Name of Authorized Transporter of Oil					
Ì	Texas-liev Maxico Pi Name of Authorized Transporter of Cas	inghead Cas Company	P. O. Box 1510, Madla Address (Give address to which appro			
Ì		 -	P. O. Box 1384, Jal,			
	El Paso Matural Gas	Unit Sec. Twp. Rge.	Is gas actually connected? Wh.			
	If well produces oil or liquids,	1 0000	1 1	i i		
		1 D 110 1259 37E	Yes	9-17-68		
	give location of tanks.	B 10 25S 37E	Yes	9-17-68		
	give location of tanks. If this production is commingled wi	B 10 25S 37E th that from any other lease or pool,		9-17-68		
	give location of tanks. If this production is commingled wi COMPLETION DATA	th that from any other lease or pool,		9-17-68 Plug Back Same Restv. Diff. Restv.		
	give location of tanks. If this production is commingled wi	th that from any other lease or pool,	give commingling order number:			
	give location of tanks. If this production is commingled wi COMPLETION DATA	th that from any other lease or pool,	give commingling order number:			
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion	th that from any other lease or pool, on - (X) Gas Well Gas Well	give commingling order number:	Plug Back Same Restv. Diff. Restv.		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion	th that from any other lease or pool, on - (X) Gas Well Gas Well	give commingling order number:	Plug Back Same Restv. Diff. Restv.		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded	on - (X) Oil Well Gas Well Date Compl. Ready to Prod.	New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded	on - (X) Oil Well Gas Well Date Compl. Ready to Prod.	New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v.		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,	on - (X) Oil Well Gas Well Date Compl. Ready to Prod.	New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,	th that from any other lease or pool, on $-(X)$ Gas Well Date Compl. Ready to Prod.	New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,	th that from any other lease or pool, on $-(X)$ Gas Well Date Compl. Ready to Prod.	New Well Workover Deepen Total Depth Top Oil/Gas Pay	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations	th that from any other lease or pool, on - (X) Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth Depth Casing Shoe		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations	th that from any other lease or pool, on - (X) Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth Depth Casing Shoe		
	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations	th that from any other lease or pool, on - (X) Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth Depth Casing Shoe		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE	New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.) Perforations HOLE SIZE	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE. (Test must be a	give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restv. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL	Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this december)	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow-		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.) Perforations HOLE SIZE	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE. (Test must be a	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow-		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks	Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be a able for this d	DEPTH SET Depth Depth	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow-		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL	Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this december)	give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff, Restv. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.)		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure	DEPTH SET Depth Depth	Plug Back Same Restv. Diff, Restv. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.)		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks	Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be a able for this d	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.) Choke Size		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.) Choke Size		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.) Choke Size		
IV.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure	give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- ift, etc.) Choke Size		
iv.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbls.	give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Depth SET Depth Set Depth Set Depth or be for full 24 hours Producing Method (Flow, pump, gas left Depth Set Depth Set Depth Set Depth Set Depth Set Depth Or Be for full Set Depth Set D	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size Gas-MCF		
iv.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbls.	give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Depth SET Depth Set Depth Set Depth or be for full 24 hours Producing Method (Flow, pump, gas left Depth Set Depth Set Depth Set Depth Set Depth Set Depth Or Be for full Set Depth Set D	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size Gas-MCF		
iv.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure Oil-Bbls. Casing and Tubing Pressure Cil-Bbls.	Rew Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Differ recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas left) Casing Pressure Water-Bbis. Bbis. Condensate/MMCF	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowiff, etc.) Choke Size Gas-MCF Gravity of Condensate		
v.	give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RXB, RT, GR, etc.,) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE Tubing Pressure Oil-Bbls. Character (Shut-in)	Rew Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Depth SET Depth Set	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowiff, etc.) Choke Size Gas-MCF		

VI.

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

C. E.	Ji O	De
Aven Engineer	Signature)	C. E. Fidler
	(Title)	

(Date)

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I, II, III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.