NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	HOW THE AREA OF CONSERVATION COMMISSION TO A	
U.S.G.S.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5a, Indicate Type of Lease
LAND OFFICE		State Fee.
OPERATOR		5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
use **APPLICATION	FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Gulf Oil Corporation		Learcy McBuffington
3. Address of Operator	24 man - 7071.F	9. Well No.
P. O. Box 980, Kerra 4. Location of Well	it, Texas 79745	10. Field and Pool, or Wildcat
v 660	South 990	Justis (Fusselman)
UNIT LETTER M. , COO	FEET FROM THE South LINE AND 990 FEET FR	OUR OLD ( FURBELINETT)
THE West LINE, SECTION	13 TOWNSHIP 25-S RANGE 37-E	
THE LINE, SECTION	TOWNSHIP RANGE NMF	.w. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3993' DF	Lea
Check An	propriate Box To Indicate Nature of Notice, Report or (	Other Date
NOTICE OF INT		NT REPORT OF:
	30532402	NI KEFOKI OF.
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON !     REMEDIAL WORK	ALIERING CASING
Ħ		21.00
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
Ħ	COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER	PLUG AND ABANDONMENT
PULL OR ALTER CASING  OTHER Plug off lower per	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER	
PULL OR ALTER CASING  OTHER Plug off lower per  17. Describe Proposed or Completed Operawork) SEE RULE 1 fos.  Propose to bridge plug in plugging off Fu	commence Drilling opns.  casing test and cement Job  other  tions (Clearly state all pertinent details, and give pertinent dates, including the pull Kobe insert pump, set a Baker Model "B 7" OD casing @ 6850' and dump a 10' cement pump asselman perforations 6860-63', 6866-69', 687, will be put back on production with perfora	" thru-tubing lug on same,
PULL OR ALTER CASING  OTHER Plug off lower per  17. Describe Proposed or Completed Operations,  Propose to bridge plug in plugging off Fu 6882-84'. Well and 6817-21' op	COMMENCE DRILLING OPPS.  CASING TEST AND CEMENT JQB  OTHER  INTUINE  CASING TEST AND CEMENT JQB  OTHER  CASING TEST AND CEMENT JQB  OTHER  OTHER  CASING TEST AND CEMENT JQB  OTHER  OTHER  OTHER  CASING TEST AND CEMENT JQB  OTHER  OTH	"thru-tubing lug on same, 4-78', and tions 6813-15'
PULL OR ALTER CASING  OTHER Plug off lower per  17. Describe Proposed or Completed Operation work) SEE RULE 1603.  Propose to bridge plug in plugging off Fu 6882-84'. Well and 6817-21' op  18. I hereby certify that the information about the second	COMMENCE DRILLING OPPS.  CASING TEST AND CEMENT JQB  OTHER  INTUINE  CASING TEST AND CEMENT JQB  OTHER  CASING TEST AND CEMENT JQB  OTHER  OTHER  CASING TEST AND CEMENT JQB  OTHER  OTH	" thru-tubing lug on same,