

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name Learcy McBuffington
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 8
4. Location of Well UNIT LETTER <u>N</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Justis Montoya
15. Elevation (Show whether DF, RT, GR, etc.) 3079' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Squeezed TA Fusselman perfs</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6933' TD. Set BP @ 6827'. Cap BP w/3 sx 20-40 frac sd (15' sd fill). Mix 40 sx Class "H" cmt, flush to spot. Pres tstd csg to 375# - OK. Tag cmt @ 6650' (46' above top perf). Drld cmt to 6808'. Tag sd on top of RBP @ 6812'. Ppd 50 sx Class "H" neat cmt to bot. Tag TOC @ 6439'. Drld cmt to 6710'. Pres tstd 400# for 15 min - OK. Drld to top of sd @ 6808'. Ppd 50 sx Class "H" neat cmt to bot. Tagged cmt @ 6559'. Drld out to 6800'. Pres test to 400# for 15 min - OK. Washed sd off RBP @ 6827'. Ppd 400 gal 20% HCl dn tbw w/acid on perfs 6754-6800'. Dumped 2 sx 20-40 sd on RBP. Set 7" 23# cmt rtnr @ 6656'. Squeeze perfs 6696-6702' & 6754-6800' w/150 sx Class "H" + .6% Halad-9. Squeeze to 2500 psi. WOC & CI 90 hrs. Drld cmt & cmt rtnr to 6800'. Wash sd off RBP. Pres csg to 300#. Ran rods & pmp. Set pkr @ 6822', SN @ 6817'. Hung well on; producing as single completion in Justis Montoya.

Work performed 7-31-79 through 10-15-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Glyn Stone TITLE Area Engineer DATE 10-17-79

APPROVED BY Orig. Signed [Signature] TITLE Jerry Sexton DATE OCT 19 1979
CONDITIONS OF APPROVAL, IF ANY: Dist. L. Supv.