Submit 5 Copies
Appropriate District Office
DISTRICT I
P.O. Bost 1980, Hobbs, NM 88240

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Azioc, NM 87410

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

REQUEST FOR ALLOWABLE AND AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS

Co								Well API No.			
ARCO 011 and Gas Company								30-025- <i>//57/</i>			
Address P.O. Box 1710 - H			dee	88241	-1710			-			
P.O. BOX 1/10 - H Reason(s) for Filing (Check proper box)	lodds, N	ew Hea	rico	00241	X Ou	et (Please expla	نانه) Chan	ge Well	Name Fr	om	
New Well	(Change in	Transpor	ter of:				_			
Recompletios	Oil		Dry Gas			•				16TONA	
Change in Operator	Casinghead	Gas 🗌	Conden	ate 📗			Effe	ctive:	1-1-	93 "	
If change of operator give name											
and address of previous operator		010									
IL DESCRIPTION OF WELL	AND LEA	SE Well No	Dool No	me Inchyli	ing Formation		Kind	of Lease	L	ease No.	
Lesse Name	1	17				ıbb Drink	0.44	Federal or Fe	_ [EE	
South Justis Unit " E	<u></u>									-	
Unit Letter	: <u>/65</u>	0	Peet Fro	en The _5	OUTH Lin	e and	<u>0</u> R	et From The	WES	7_Line	
Section /3 Townshi	p 25S	<u> </u>	Range	37	E N	мрм,	<u>Lea</u>			County	
III. DESIGNATION OF TRAN	SPORTE	OF OI	L ANI	NATU	RAL GAS						
Name of Authorized Transporter of Oil	רצו '	or Condens	sate [Address (Giv	e address to wh	ich approved	copy of this fo	orm is to be se	rd)	
Texas New Mexico Pineline Company						P.O. Box 2528 - Hobbs, NM 88241-2528 Address (Give address to which approved copy of this form is to be sent)					
Name of Authorized Transporter of Casinghead Gas					1						
	id Richardson Carbon and Gasoline Company					y connected?	- Jal, When	NM 88252			
If well produces oil or liquids, give location of tanks.	Unit	Sec.	Twp	i Kir		ES	•	NNINE	14/11		
If this production is commingled with that	from any other	r lease or r	ood, give	comming		·	_				
IV. COMPLETION DATA	HOLL TRY CON					many and the	<u>*</u>				
Designate Type of Completion		Oil Well	G	as Well	New Well	Workover	Deepea	Plug Back	Same Res'v	Diff Res'v	
Date Spudded	Date Compl. Ready to Prod.			Total Depth			P.B.T.D.				
Elevations (DF, RKB, RT, GR, etc.)	Name of Producing Formation				Top Oil/Gas Pay			Tubing Depth			
Perforations								Depth Casing Shoe			
			<u> </u>	- 11m	CC) (C) PI	IC DECOR	<u> </u>	<u> </u>	 		
	TUBING, CASING AND CASING & TUBING SIZE				DEPTH SET			SACKS CEMENT			
HOLE SIZE	CASING & TODING SIZE										
	 			······································							
					<u> </u>			<u> </u>	· · · · · · · · · · · · · · · · · · ·		
V. TEST DATA AND REQUES	T FOR A	LLOWA	BLE		L	annead ton allo	unde for this	don't ar he f	or full 24 hour	-e 1	
OIL WELL (Test must be after recovery of total volume of load oil and must						be equal to or exceed top allowable for this depth or be for full 24 hours.) Producing Method (Flow, pump, gas lift, etc.)					
Date First New Oil Run To Tank	Date of Test					(a (a))		•			
Length of Test	Tubing Pressure				Casing Pressure			Choke Size			
Actual Prod. During Test	Oil - Bbis.				Water - Bbis.			Gas- MCF			
GAS WELL	<u> </u>				<u></u>						
Actual Prod. Test - MCF/D	Length of Test				Bbls. Condensate/MMCF			Gravity of Condensate			
Testing Method (pilot, back pr.)	Tubing Pressure (Shut-in)				Casing Pressure (Shut-in)			Choke Size			
VI. OPERATOR CERTIFIC I bereby certify that the rules and regul. Division have been complied with and is true and complete to the best of my 1	ations of the C	Dil Conserv nation give	ration	CE	11	OIL CON		ATION I Jan	DIVISIO 99	N J3	
1-10	1.					• •					
Signature - Operations Coordinator					By ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR						
Printed Name Printed Name 1 - 04 - 93	•	(505) _	Title		Title	DECO	DD /	7 NII V	ĵvá 1€°.	1841 Sec. 2015	
	<u>`</u>	7.1.	Shope No		 C OR	RECO	バレし	JNLT	1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	25 1949	

INSTRUCTIONS: This form is to be filed in compliance with Rule 1104

- 1) Request for allowable for newly drilled or deepened well must be accompanied by tabulation of deviation tests taken in accordance with Rule 111.
- 2) All sections of this form must be filled out for allowable on new and recompleted wells.
- 3) Fill out only Sections I, II, III, and VI for changes of operator, well name or number, transporter, or other such changes.

RECEIVED

APR 9 8 1993

SU NUBBE UT

RECEIVED

Times in James

> 5 **1993**

OND HOSBS OF D