

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM051998

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carlson B-13

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix (7 Rivers Queen)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 13, T25S, R37E NMPM

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Terra Resources, Inc.

3. ADDRESS OF OPERATOR

10 Desta Drive, Suite 500 West Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

2310' FNL, 660' FEL Sec. 13
SE/4, NE/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3088 RT

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Set CIBP @ 3300' w/100' cement on top (spot via tbg)
- 2) Spot 10 sx plug 2250' - 2350 (spot via tbg)
- 3) Perforate 5-1/2" casing @ 1175' and set retainer at 1075'. Circulate cement to surface with 200 sx Class "C" cement. (Leave 35' CMT on Retainer) sss
- 4) Cut off casing and spot 10 sx, plug at surface.
- 5) Erect plug and Abandon marker

RECEIVED
JUL 7 11 13 AM '87
CARLSON RESOURCE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

Shirley Ayner

TITLE

Operations Engineer

DATE

(This space for Federal or State office use)

APPROVED BY

John A. Anderson

TITLE

DATE

7-10-87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
JUL 13 1997
OCD
HOBBS OFFICE