

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE MANNER
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. L.C. 032579(6)	
2. NAME OF OPERATOR CRA, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NM 051998	
3. ADDRESS OF OPERATOR Box 33, Jal, New Mexico		7. UNIT AGREEMENT NAME Lease	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' Fr. N. & 1980' Fr. E. Line Sec. 13		8. FARM OR LEASE NAME Carlson B 13	
14. PERMIT NO.		9. WELL NO. 5	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 3099		10. FIELD AND POOL, OR WILDCAT Justis	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13 258 37E NMPM	
		12. COUNTY OR PARISH Lea	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☒	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-3-65 - Drilled BP #5228'. Set Baker cast iron BP #6010' w/one sack cement. Run cement bond log. Squeeze Hlinebry w/250 sack D-60 thru perfs. 5254' Pkr. #5100' Squeeze Paddock perfs. 4960-4995' w/200 sack D-60 Pkr. #4858'. Drill out to 5900' Test Hlinebry. Squeeze w/90 sack D-60 Perf. 4 holes 5514'-5515' squeeze w/80 sack D-60 Pull up squeeze Paddock w/70 sack D-60. W.O.C. Drill out to 5510'. Test csg. 1000# for 1 hr. Held 0, K. Perf. Hlinebry 5254'-5449' Frac w/25,000 gal. lease oil and 25,000# sand, spearhead w/5000 gal. NE. Acid. Rec. load oil. Well made 180 BO in 14 hrs. no water on 16/64". Perf. Paddock 6 holes 4959'-67'-70'-78'-84'-90'. Set model D prod. pkr. #5224'. Acidize w/3500 gal NE. & 8 ball sealers. Well flowed 15 BO and 3 BW in 5 1/2 hr. Kill well. Run dual 2 1/16" prod. strings. Dual well Hlinebry-Paddock. Job complete 6-2-65.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. C. Chaffin

TITLE

Prod. Supt.

DATE

6-2-65

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.