DEPARTMEN i OF TH	E INTERIOR HOBBS. NEW MEXICO	Budget Bureau No. 1004-0135 Expires September 10, 1990
DEPARTMEN I OF THE INTERIOR HOBBS. NEW MEXICO SUNDRY NOTICES AND REPORTS ON WELLS DEPARTMEN I OF THE INTERIOR HOBBS. NEW MEXICO SUNDRY NOTICES AND REPORTS ON WELLS Use "APPLICATION FOR PERMIT" for such proposals		5. LEASE DESIGNATION AND SERIAL NO. NM-14215
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUBMIT IN TRIPLICATE 1. TYPE OF WELL GAS WELL OTHER		7. IF UNIT OR CA, AGREEMENT DESIGNATIO
		8. WELL NAME AND NO.
2. NAME OF OPERATOR		South Justis Unit "D" #18
ARCO Oil & Gas Company		9. API WELL NO.
3. ADDRESS AND TELEPHONE NO.		30-025-11581
P.O. Box 1610, Midland, TX 79702	(915) 688-5672	10. FIELD AND POOL, OR EXPLORATORY ARE
4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Descri	ption)	Justis Blbry-Tubb-Dkrd
330 FSL & 330 FEL (Unit Letter P) 14-25S-37E		11. COUNTY OR PARISH, STATE Lea
CHECK APPROPRIATE BOX(S) TO II	NDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF A	
NOTICE OF INTENT	ABANDONMENT	CHANGE OF PLANS
		NEW CONSTRUCTION
X SUBSEQUENT REPORT		NON-ROUTINE FRACTURING
	CASING REPAIR	WATER SHUT-OFF
FINAL ARANDONMENT NOTICE		
FINAL ABANDONMENT NOTICE	ALTERING CASING	CONVERSION TO INJECTION
DESCRIBE PROPOSED OR COMPLETED OBEDATIONS (S)	ALTERING CASING Workover w (NOTE: Report resi	CONVERSION TO INJECTION ellbore for South Justis Unit ults of multiple completion on Well or Recompletion Report and Log form.)
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly proposed work. If well is directionally drilled, give subsurface local developments of the subsurface local	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for	ellbore for South Justis Unit ults of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.)
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly a proposed work. If well is directionally drilled, give subsurface lost 4-19-93. RUPU. POH w/CA. Mill out junk. DO	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for	ellbore for South Justis Unit ults of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.)
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly a proposed work. If well is directionally drilled, give subsurface lost 4-19-93. RUPU. POH w/CA. Mill out junk. DO	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for	ellbore for South Justis Unit ults of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.)
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sproposed work. If well is directionally drilled, give subsurface locally drilled. Give subsubsurface locally drilled. Give subsurface locally dril	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for	conversion to injection ellbore for South Justis Unit justs of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.) 6037. Press test csg to 500#.
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly proposed work. If well is directionally drilled, give subsurface location and the subsurfac	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for CR & cmt to 5975 PBD. RIH w/RBP to 5 Is & pump to 5923. RDPU 4-24-93.	ellbore for South Justis Unit pults of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.) 6037. Press test csg to 500#.
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly: proposed work. If well is directionally drilled, give subsurface loc 4-19-93. RUPU. POH w/CA. Mill out junk. DO POH w/RBP. RIH w/CA: 2-3/8 tbg, rod I hereby certify that the foregoing is true and correct SIGNED	ALTERING CASING Workover w (NOTE: Report res Completion state all pertinent details, and give pertinent dates cations and measured and true vertical depths for CR & cmt to 5975 PBD. RIH w/RBP to 5 Is & pump to 5923. RDPU 4-24-93.	conversion to injection ellbore for South Justis Unit uits of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this work.) 6037. Press test csg to 500#.