			•	•
Form 9-331 (May 1963)	. Ui	N D STATES	SUBMIT IN TRIPI	Form approved.
(222) 1000)		NT OF THE INTER		
GEOLOGICAL SURVEY				
				LC060943
SUNDRY NOTICES AND REPORTS ON WELLS				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use th				
1. OIL V GAS	other Dua			7. UNIT AGREEMENT NAME
WELL A WELL				
2. NAME OF OPERATOR	8. FARM OR LEASE NAME			
Atlantic Ri	Langlie Federal			
3. ADDRESS OF OPERAT	9. WELL NO.			
P. O. Box 1710, Hobbs, New Mexico 88240  4. LOCATION OF WILL (Report location clearly and in accordance with any State requirements.*				2 7
esec gran shace 14 ht	10. FIELD AND POOL, OR WILDCAT			
At surface				Justis/Blinebry Tubb D
	_			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
1650' FSL 8				
14. PERMIT NO. 15 EIPUATIONS (Show whether DE 70 cm atc.)				Sec 14, T25S, R37E
111 122211 110.	1	5. ELEVATIONS (Show whether DF	• •	12. COUNTY OR PARISH 13. STATE
		3125' RKE	3	Lea N.M.
16.	Check Appro	priate Box To Indicate N	lature of Notice, Report, o	or Other Data
	NOTICE OF INTENTION			SEQUENT REPORT OF:
TEST WATER SHUT-				
FRACTURE TREAT		OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE	1	TIPLE COMPLETE	FRACTURE TREATMENT	X ALTERING CASING
SHOULING OR ACIDIZING				ABANDONMENT <sup>®</sup> Tubb Drkd
(Other) (Note: Report results of				ults of multiple completion on Well
17. DESCRIBE PROPOSED O	R COMPLETED OPERATION	ONS (Clearly state all pertinen	Completion or Reco	ompletion Report and Log form.)
proposed work. I nent to this work.)		drilled, give subsurface locat	tions and measured and true ver	tes, including estimated date of starting any rtical depths for all markers and zones perti-
12/12/73 - Ran	latch-type I	OR nlug set in 415	D nkr @ 5790! Co.	pped w/35' cmt. New PBD is
5755'. Tubb D	rkd zone P&A	on 12/7/73 Parf	orated Justic Pline	pped w/33 Cmt. New PBD 18
5755'. Tubb Drkd zone P&A on 12/7/73. Perforated Justis Blinebry 5141, 45, 49, 58, 65, 82, 84, 89, 96, 5212, 16, 27, 32, 42, 54, 61				61 81 5307 33 50 5500
12, 16, 22 & 5524'. Ran pkr & BP @ 5546'. Spotted 84 gals 15% HG				WHCl-ISTNE actd across porfe
<b>5507-</b> 5522'. T	id. Ret BP & reset @ 5484'.			
Trtd perfs 536	reset @ 5359' Snotted 84			
Trtd perfs 5363-5454' w/1000 gal 15% HCl-LSTNE acid. Ret BP & reset @ 5359'. Spotted 8 gals 15% HCl-LSTNE acid across perfs 5141-5350'. Trtd perfs 5141-5350' w/1500 gals HCl-				
LSTNE. Ret BP	. Trtd perfs	5141-5524' w/75.	000# 20/40 sd & 50	,000 gal slick 9# brine
containing 20#	/1000 gal gel	l. 25#/1000 gal Ad	omite Aqua 🚦 gal/1	1000 gal de-emulsifier &
250# benzoic a	cid in 2 stag	res. Rel nkr. & P	OH w/tho WIH w/2-	-3/8" buttress tbg = 5356.99
set @ 5366.32'	. Swbd back	well. well would	not flow. Ran Kobe	e pump on 3/4" N-80 Kobe tbg
Pump set @ 525	2.90'. On te	est $1/23/74$ pmpd 2	3 BO & 40 BW in 24	hrs. Returned to production
as single comp	letion.in Bli	nebry perfs 5141-	5524'.	
				o Tables  Called Addition  Called Additi
		•		oval of Entro Entr
				hindha of oldar of cherry results and the foldar oldar oldar oldar androd androd androd
				Services of the services of th
				m yot habily half half half half half half half half
				mella you home of home of home of home of home of the color of the col
90 <b>1</b>				on looking to abbooks! of longiting of partial state of the state of t
18. I hereby certify that	the foregoing is to	and correct	····	
1/./	- /- )		24 22-1 2	
SIGNED	1 then	TITLE Dis	st. Drlg. Supv.	DATE 2/25/74
(This space for Fede	ral or State office use	1 6	547 10 10 m	YXXII
ADDBOURN NW			130 -1 - 1 074 ()	
CONDITIONS OF A	PROVAL, IF ANY:	TITLE		DATE TO THE PARTY OF THE PARTY

"See Instructions on Reverse Side