to Appropriate
District Office

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe, New Mexico 87504-2088

5. Indicate Type of Lease

F.O. DIAWA DD, 744441, Table Care	SIXIE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	Christmas SWD
OIL GAS WELL OTHER SWD	8. Well No.
2. Name of Operator	-1-
Bettis, Boyle & Stovall 3. Address of Operator	9. Pool name or Wildcat
P.O. Box 1240, Graham, TX 76450-7240	Jalmat SR-Q
4. Well Location Unit Letter _ E : _ 1650 Feet From The North Line and 330 Feet From The West Line	
	NMPM Lea County
Section 20 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
CASING TEST AND C	EMENT JOB 🔀
OTHER on 4-1	/2" liner
OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
8/25/92 - MIRU Gene's Well Ser., POOH & Lay down 2-3/8" tbg & 7" pkr., NU BOP, TIH & drill out fill to original TD of 3285'. Circ. hole clean. Run scraper in hole.	
8/26/92 - TIH w/ 4-1/2X6-1/8" formation pkr. shoe, 74 jts, 9.5# 4-1/2" csg., land csg @ 2955'. RU Halliburton Co. & cement liner w/ 160 sx. Halliburton Lite, 2% CC + 1/4% Halad 9. Tail in w/ 100 sx Prem + 2% CC. Plug down @ 6 PM. Did not circ. cement.	
8/27/92 - RU JSI Ser. & run temp. survey. Survey showed TOC @ 2370'. Perf 4 holes @ 2300'. RU pump truck, pumped dye & 460 BW, did not see dye @ surface. RU to pump cement as follows pump 20 bbls. 10% CC wtr., 24 bbls flochek, 250 sx Halliburton, Lite cement w/ 9# salt per sk, 3% CC, tail in with 50 sx Prem + 2% CC, drop wiper plug, flush to 2250, good returns but cement did not circ.	
Dut Coment at a more and a more a	page 194
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
me Production	Analyst
SIGNATURE 817	-549-0780 теlернопе по.
TYPE OR PRINT NAME Kim Ligon 817-349-0780	
CONTRACTOR STATIONAL SIGNED BY JERRY SEXTON	•

BISTRIGT I SUPERVISOR

SEP 28'92 _ DATE -

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY -

RECEIVED
SEP 2 5 1992
OCD HOBBS OFFICE