

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co's. Division
P.O. Box 196
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ARCO Permian

3. Address and Telephone No.

P.O. Box 1710 Hobbs, N.M. 88240

505-394-1649

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FSL & 330 FEL (Unit Letter I)
23-25S-37E

5. Lease Designation and Serial No.

LC-060945

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

NMNM87877X

Field South Justis Unit

8. Well Name and No.

D-21 SOUTH JUSTIS UNIT 30-025-1

9. API Well No.

1704 30-025-1704

10. Field and Pool, or exploratory Area

Justis Bly Tubb Drkd

11. County or Parish, State

Lea

NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Add Perfs & Acidize
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD: 6050' PBD: 6014' PERFS: 5024-5708

12/17/96: POH w/2-3/8" tbg.

12/18/96: WIH w/bit, sub, scraper, & 2-7/8" workstring.

12/19/96: WIH w/4" gun shot perf 1 SPF 5024-5039, 13 holes. Set pkr @ 5041'. Pmp 32 bbls

2% KCL down tbg. Acidize existing perfs from 5048 to 5708' w/1000 gals 15% NEFE HCL. Set

pkr @ 5031'. Acidize new perfs from 5024-5039' w/1000 gals 15% NEFE HCL.

12/20/96: WIH w/tbg. Ran pmp & rods. Loaded tbg to 5000', press held OK.

~~12/17/96: POH w/2-3/8" tbg.~~

~~12/18/96: WIH w/bit, sub, scraper, & 2-7/8" workstring.~~

~~12/19/96: WIH w/4" gun shot perf 1 SPF 5024-5039, 13 holes. Set pkr @ 5041'. Pmp 32 bbls~~

~~2% KCL down tbg. Acidize existing perfs from 5048 to 5708' w/1000 gals 15% NEFE HCL. Set~~

~~pkr @ 5031' field~~

ACCEPTED FOR RECORD

APR 03 1997

acc

RECEIVED

MAR 26 97

BLM
ROSWELL, NM

On prod?

Back on Relin
per 410-97

14. I hereby certify that the foregoing is true and correct

Signed Kevin H. Murrish

Title Administrative Asst.

Date 3-25-97

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: