

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIU
(Other instructic
verse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 060945

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carlson "A" Federal

9. WELL NO.

2

10. FIELD AND POOL OR WILDCAT

Blinebry
Justis - Tubb/Drinkard11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

23-258-37E

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1978, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1650' FEL (Unit Letter J)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3087' DF

12. COUNTY OR PARISH

Lee

18. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 12/10/66 pulled completion assembly from this dual well. Added Blinebry perforations @ 5203', 5216', 5222', 5229', 5245', 5248', 5267', 5281' & 5282' (Schl. log) w/one 3/8" OD jet shot. Treated down 2-7/8" tubing w/2000 gal. 15% HCl & swabbed back. Fraced w/25,000 gal. of lease crude containing 29,300# of 20/40 sand. Avg TP=5300#, AIR=14 BPM, ISIP=1300#. Swabbed & flowed all of load. On 27 hour test ending @ 7:00 AM 12/17/66 Blinebry zone flowed 244 BO & 10 BW on 20/64" choke. FTP=300#. Ran Tubb/Drinkard zone tubing of 186 jts 2-3/8" OD 4.6# J-55 B.T. w/Kobe shoe and seal assembly. Bottomed @ 5780.31'. Set in Baker 415-D packer w/7000# of weight. Ran Blinebry tubing of 172 jts of 2-3/8" OD J-55 4.6# B.T. Bottomed @ 5321.16' RKB. No work was performed on Tubb/Drinkard formation.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Drilling Supervisor

DATE

12-19-66

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

DEC 20 1966

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1969-O-365229
967-931

DEC 15 1969
FEDERAL BUREAU OF INVESTIGATION
U.S. DEPARTMENT OF JUSTICE