Form <u>9–</u> 331 Dec. 1973		. M. DIL CONS. COMMENSION		Form Approved. Budget Bureau No. 42–R1424
i	UNITED SE DEPARTMENT OF F	ATESBOX 1989 HEITNTÉRIOR	. 5. LEASE IC-032650 (b	
	GEOLOGICAL S	SURVEY		LOTTEE OR TRIBE NAME
(Do not use this fo	rm for proposals to drill or t	REPORTS ON WELLS	7. UNIT AGREEM	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			8. FARM OR LEASE NAME A.B. Coates "C"	
2. NAME OF OPERATOR			9. WELL NO.	6
	Getty Oil Company 3. ADDRESS OF OPERATOR			DCAT NAME
4. LOCATION (below.)	728, Hobbs, N.M.	11. SEC., T., R., M AREA Sec. 24, T-25	A., OR BLK. AND SURVEY OR	
	DD. INTERVAL:	660' FNL & 1980' FEL	12. COUNTY OR F	PARISH 13. STATE
16. CHECK APP REPORT, OF	ROPRIATE BOX TO INI	DICATE NATURE OF NOTICE,	14. API NO.	
REQUEST FOR A		UBSEQUENT REPORT OF:	15. ELEVATIONS 3083' D.F.	(SHOW DF, KDB, AND WD)
TEST WATER SH FRACTURE TREA SHOOT OR ACID REPAIR WELL PULL OR ALTER MULTIPLE COMP CHANGE ZONES ABANDON* (other)			(NOTE: Report resu change on (Its of multiple completion or zone Form 9–330.)
measured an Rigged up. Pull Set 7" CIBP at 5	d true vertical depths for led rods and pump 5650'.	TED OPERATIONS (Clearly stat any proposed work. If well is d r all markers and zones pertiner p. Installed BOP. P	ulled tbg.	ve subsurface locations and
Acidized perfs v Fraced 7" csq. r	nith 2215 gal. NF xith 4886-4994'	(Paddock Zone) with	28 000 001 404	V Témle seles 1
Flush w/2000 gal Installed pumpir	. 28 KCI.	ugged Justis Tubb Dr	2 stages w/12	BS between stages.
Subsurface Safety	Valve: Manu. and Type			Set @ Ft.
18. I hereby certification \mathcal{W} .	by that the foregoing is tri \mathcal{B} .	ue and correct	•	May 6, 1985
		(This space for Federal or State offi		
APPROVED BY	ACCEPTED FOR RI	ECOND- =		I
	Aux		C. C	N.
	MAY 10 198	5 *See Instructions on Reverse Si	de	

•

- -

CARISBAD,	NE	MEXICO
-----------	----	--------

1. 2. 3.

4. 5.

6.

·* --

· · · · · · ·