UNI D STATES SUBMIT IN TRIPLIC May 1963) DEPARTMENT OF THE (INTERIOR verse side) GEOGRAFICAT SURVEY					a. LEAS	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. LC-032650 (b)			
(1		TON YS	ICES, AND REN	dans on	WELLS o a different reservoir.	6, IF IS	DIAN, ALLOTT	EE O' TRIBE NAME	
1. OIL WELL	X GAS WELL	OTHER				7. UNIT	AGREEMENT 1	NAME	
2. NAME	NAME OF OPERATOR				S. PARS	N. FARM OR LEASE NAME			
	Tidewater	Oil Con	npany			Α.	B. Coate	es C	
3. ADDRE	SS OF OPERATOR					9. WEL	. So.		
•		Hobbs.	New Mexico 882	+0		1 6			
See al	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FVL and 1980' FEL					Jus	Justis Ellenburger 11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA Sec. 24, T25S, R37E		
14. PERM	IT NO.		15, ELEVATIONS (Show		R, etc.)	1	NTY OR PARIS	New Mexico	
16.		Check A	ppropriate Box To I	ndicate Natur	e of Notice, Report,	or Other Do	zta		
	NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
	TWATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING		

(Other)

(Other)

(Note: Report results of multiple completion on Well
Controlled on Recompletion Report and Log form.)

17. Describe Proposed on Completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SHOOTING OF ACIDIZING

(Other) Install Gas Lift Valves

Killed well, pulled tubing and packer. Redressed packer, ran back in hole with tubing and 8 USI gas lift valves on Type "A" mandrels. Connected gas line and started gas lifting.

SHOOT OR ACIDIZE

REPAIR WELL

18. I hereby certify that the foregoing is true and c	orrect		
SIGNED C. 4. DE		Area Supt.	DATR 11-11-66
(This space for Federal or State office use)			APPROVED
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	THE		DATE

NOV 15 1966