

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-032650 (b)
2. NAME OF OPERATOR Getty Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 730, Hobbs, NM 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FSL & 1650 FWL		8. FARM OR LEASE NAME A.B. Coates "C"
14. PERMIT NO.		9. WELL NO. 12
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3084' DF		10. FIELD AND POOL, OR WILDCAT
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 24, T-25S, R-37E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Down hole Commingled Tubb-Drinkard & Fusselman

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/14/84 Commingled. Rig up Gene's Well Service. Lay down Tubb rods. Pull Fusselman rods.
9/15/84 Layed down short string (Tubb) (Drinkard). Tried to release deep side latch seal assembly. POH. (Left seal assembly, 1 jt of tbg and SN).
9/16/84 Ran model pkr on 2 3/8" tbg and set @ 6466'. Acid Engr. acidized perfs 6252-6702'. Fusselman, with 3000 gals 15% and 75 gal pentafax and 25 ball sealers. Max 1800#, avg. 75#, SI vacuum, total load 128 bbls. Rate 4 BPM. Pull pkr. Ran 2 3/8" tbg. Set @ 6516'. SN @ 6485', anchor @ 6422'.
9/17/84 Ran 2 x 1 1/2 x 22 pump on 161 3/4" and 97 7/8" rods. Start pumping 9 x 120 SPM.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Superintendent

DATE September 3, 1984

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL NOV 27 1984

0+6-BLM-Carlsbad 1-Mr. J.A.-Midland

1-File, 1-Engr Jim, 1-Foreman CK,

1-BB, 1-JA, 1-BK, 1+SH, 1-CPD *See Instructions on Reverse Side